

NEW MEXICO OIL CONSERVATION DIVISION
P.O. BOX 1000
ARTESIA, NEW MEXICO 88210

RECEIVED

DWIB 11-11-88

Signature _____

Box 811, Suite 400

FEB 17 '89

Houston, TX 77002

O. C. D.
ARTESIA, OFFICE

Re: _____

Form G-103 Report of Plugging for your Gardner Draw Ut #2 _____
Lease _____ Well _____

Work is approved until an N.M.O.C.D. representative has made _____
location and found it to be cleared to comply with Division _____
requirements. Please check each item in the space provided to indicate _____

- ✓ 1. All pits have been filled and leveled.
- ✓ 2. Surface and cellar have been filled and leveled.
- ✓ 3. A steel marker 4" in diameter and approximately 11" high bearing _____
level has been set in concrete. It must show the quarter-quarter _____
section or unit designation, section, township and range numbers _____
have been permanently stenciled or welded on the marker.
- ✓ 4. The location has been leveled as nearly as possible to adjacent _____
ground contour and has been cleared of all junk and debris.
- ✓ 5. The dead men and tie downs have been cut and removed.
- ✓ 6. If a one well lease or last remaining well on 1/4 section, _____
burn pit locations have been leveled and cleared _____

_____ are minimum requirements and no plugging bond will be _____
_____ for plugged and abandoned wells have been inspected and _____

_____ of the work outlined above has been done, please notify _____
_____ and _____ below and returning this letter to us so that our _____
_____ more than one trip to the location.

OIL CONSERVATION DIVISION

Mike [Signature]
SUPERVISOR

_____ RETURN _____

_____ that the above work has been done and the above mentioned _____
_____ and approved.

Rough [Signature]
PRODUCTION FOREMAN