CONS. COMMISSION UNITED STATES	Burget Eruread No. 40-R1414 5. LEÁSE
, NM 88210 DEPARTMENT OF THE INTERIOR	NM-6019
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME
1. oil gas other P&A RECEIVED BY	Kinyan Fed Com
	9. WELL NO.
2. NAME OF OPERATOR Mesa Petroleum Co. MAY 11 1987	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Runyan Ranch ABO
P.O. Box 2009/Amarillo, Texas 79189 O.C.D.	11. SEC., T., R., M., OR BLK. AND SURVEY OF
4. LOCATION OF WELL (REPORT LOCATION CLEARIARTS AND ALL CREATED AND ALL CREATE	AREA
below.) AT SURFACE: 1980' FNI & 660' FUI	Sec 17, T19S, R23E 12. COUNTY OR PARISH 13. STATE
AT SURFACE: 1980' FNL & 660' FWL AT TOP PROD. INTERVAL: _	Eddv New Mexico
AT TOTAL DEPTH: same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	30-015-22561
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	4062' GR
TEST WATER SHUT-OFF	
FRACTURE TREAT	
	(NOTE: Report results of multiple completion or zon-
PULL OR ALTER CASING D FEB 2	change on Form 0.330)
MULTIPLE COMPLETE Image: Change zones Image: Change zones	0.1903
ABANDON* 🗌 🖾 🕅	Gre
(other) MINERALS MC	MT. SEPROF
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat	te all tertinent details and give pertinent dates
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statistic including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine	directionally drilled, give subsurface locations and
including estimated date of starting any proposed work. If well is a	directionally drilled, give subsurface locations and nt to this work.)*
including estimated date of starting any proposed work. If well is or measured and true vertical depths for all markers and zones pertine	directionally drilled, give subsurface locations and nt to this work.)* follows:
including estimated date of starting any proposed work. If well is of measured and true vertical depths for all markers and zones pertine Commenced P&A operations at 0800 2-21-83 as Set CIBP at 4447' (ABO perfs at 4496' - 4646 from 4447' to 4197'.	directionally drilled, give subsurface locations and nt to this work.)* follows:
including estimated date of starting any proposed work. If well is of measured and true vertical depths for all markers and zones pertine Commenced P&A operations at 0800 2-21-83 as Set CIBP at 4447' (ABO perfs at 4496' - 4646 from 4447' to 4197'. Set 25 sx "C" from 2800' to 2550'.	directionally drilled, give subsurface locations and nt to this work.)* follows:
including estimated date of starting any proposed work. If well is of measured and true vertical depths for all markers and zones pertine Commenced P&A operations at 0800 2-21-83 as Set CIBP at 4447' (ABO perfs at 4496' - 4646 from 4447' to 4197'. Set 25 sx "C" from 2800' to 2550'. Set 25 sx "C" from 1800' to 1550'.	directionally drilled, give subsurface locations and nt to this work.)* follows: ') and spotted 25 sx "C"
including estimated date of starting any proposed work. If well is of measured and true vertical depths for all markers and zones pertine Commenced P&A operations at 0800 2-21-83 as Set CIBP at 4447' (ABO perfs at 4496' - 4646 from 4447' to 4197'. Set 25 sx "C" from 2800' to 2550'. Set 25 sx "C" from 1800' to 1550'. Ran 1" down 5 1/2" CSG annulus and pumped 100	directionally drilled, give subsurface locations and nt to this work.)* follows: ') and spotted 25 sx "C" 0 sx "C" between 5 1/2" and
including estimated date of starting any proposed work. If well is of measured and true vertical depths for all markers and zones pertine Commenced P&A operations at 0800 2-21-83 as Set CIBP at 4447' (ABO perfs at 4496' - 4646 from 4447' to 4197'. Set 25 sx "C" from 2800' to 2550'. Set 25 sx "C" from 1800' to 1550'.	directionally drilled, give subsurface locations and nt to this work.)* follows: ') and spotted 25 sx "C" 0 sx "C" between 5 1/2" and to surface.
including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine Commenced P&A operations at 0800 2-21-83 as Set CIBP at 4447' (ABO perfs at 4496' - 4646 from 4447' to 4197'. Set 25 sx "C" from 2800' to 2550'. Set 25 sx "C" from 1800' to 1550'. Ran 1" down 5 1/2" CSG annulus and pumped 10 8 5/8" CSG at 1700' and 25 sx "C" from 250' Set 125 sx "C" from 850' to surface. Instal Well is P&A at 2000 2-21-83.	directionally drilled, give subsurface locations and nt to this work.)* follows: ') and spotted 25 sx "C" 0 sx "C" between 5 1/2" and to surface.
including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine Commenced P&A operations at 0800 2-21-83 as Set CIBP at 4447' (ABO perfs at 4496' - 4646 from 4447' to 4197'. Set 25 sx "C" from 2800' to 2550'. Set 25 sx "C" from 1800' to 1550'. Ran 1" down 5 1/2" CSG annulus and pumped 100 8 5/8" CSG at 1700' and 25 sx "C" from 250' Set 125 sx "C" from 850' to surface. Instal	directionally drilled, give subsurface locations and nt to this work.)* follows: ') and spotted 25 sx "C" 0 sx "C" between 5 1/2" and to surface.
including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine Commenced P&A operations at 0800 2-21-83 as Set CIBP at 4447' (ABO perfs at 4496' - 4646 from 4447' to 4197'. Set 25 sx "C" from 2800' to 2550'. Set 25 sx "C" from 1800' to 1550'. Ran 1" down 5 1/2" CSG annulus and pumped 10 8 5/8" CSG at 1700' and 25 sx "C" from 250' Set 125 sx "C" from 850' to surface. Instal Well is P&A at 2000 2-21-83.	directionally drilled, give subsurface locations and nt to this work.)* follows: ') and spotted 25 sx "C" 0 sx "C" between 5 1/2" and to surface. led Dry Hole Marker.
<pre>including estimated date of starting any proposed work. If well is of measured and true vertical depths for all markers and zones pertine Commenced P&A operations at 0800 2-21-83 as a Set CIBP at 4447' (ABO perfs at 4496' - 4646 from 4447' to 4197'. Set 25 sx "C" from 2800' to 2550'. Set 25 sx "C" from 1800' to 1550'. Ran 1" down 5 1/2" CSG annulus and pumped 100 8 5/8" CSG at 1700' and 25 sx "C" from 250' Set 125 sx "C" from 850' to surface. Install Well is P&A at 2000 2-21-83.</pre>	directionally drilled, give subsurface locations and nt to this work.)* follows: ') and spotted 25 sx "C" 0 sx "C" between 5 1/2" and to surface. led Dry Hole Marker. Set @ F
<pre>including estimated date of starting any proposed work. If well is of measured and true vertical depths for all markers and zones pertine Commenced P&A operations at 0800 2-21-83 as a Set CIBP at 4447' (ABO perfs at 4496' - 4646 from 4447' to 4197'. Set 25 sx "C" from 2800' to 2550'. Set 25 sx "C" from 1800' to 1550'. Ran 1" down 5 1/2" CSG annulus and pumped 100 8 5/8" CSG at 1700' and 25 sx "C" from 250' Set 125 sx "C" from 850' to surface. Install Well is P&A at 2000 2-21-83.</pre>	directionally drilled, give subsurface locations and nt to this work.)* follows: ') and spotted 25 sx "C" 0 sx "C" between 5 1/2" and to surface. led Dry Hole Marker. Set @ F
<pre>including estimated date of starting any proposed work. If well is of measured and true vertical depths for all markers and zones pertine Commenced P&A operations at 0800 2-21-83 as a Set CIBP at 4447' (ABO perfs at 4496' - 4646 from 4447' to 4197'. Set 25 sx "C" from 2800' to 2550'. Set 25 sx "C" from 1800' to 1550'. Ran 1" down 5 1/2" CSG annulus and pumped 100 8 5/8" CSG at 1700' and 25 sx "C" from 250' Set 125 sx "C" from 850' to surface. Install Well is P&A at 2000 2-21-83.</pre>	<pre>directionally drilled, give subsurface locations and nt to this work.)* follows: ') and spotted 25 sx "C" 0 sx "C" between 5 1/2" and to surface. led Dry Hole Marker</pre>
<pre>including estimated date of starting any proposed work. If well is of measured and true vertical depths for all markers and zones pertine Commenced P&A operations at 0800 2-21-83 as a Set CIBP at 4447' (ABO perfs at 4496' - 4646 from 4447' to 4197'. Set 25 sx "C" from 2800' to 2550'. Set 25 sx "C" from 1800' to 1550'. Ran 1" down 5 1/2" CSG annulus and pumped 100 8 5/8" CSG at 1700' and 25 sx "C" from 250' Set 125 sx "C" from 850' to surface. Install Well is P&A at 2000 2-21-83.</pre>	<pre>directionally drilled, give subsurface locations and nt to this work.)* follows: ') and spotted 25 sx "C" 0 sx "C" between 5 1/2" and to surface. led Dry Hole Marker</pre>

*See Instructions on Reverse Side