

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

MAR 16 1982

O. C. D.

ARTESIA, OFFICE

Form C-103  
Revised 10-1-70

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
LG-5096

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name Eddy "IL" State Com
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER E, 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 30 TOWNSHIP 19S RANGE 29E NMPM.	10. Field and Pool, or Wildcat Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.) 3323' GL	12. County Eddy

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with packer and tubing. Set CIBP at 5390', test 500#; cap with 35' cement. Cut casing off 10' above free point, POH with casing. Circulate hole with abandonment mud. Spot 100' cement plug half in and half out of casing stub. Spot 100' cement plug ~~4175'-4075'~~ <sup>4175'-4075'</sup> 4175'-4075'. Spot cement plug 3130'-3030'. Spot cement plug 2985'-2885'. Spot 10 sack surface plug. Erect dry hole marker. Clear and clean location as required.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Russell Worley TITLE Area Engineer DATE 3-15-82

APPROVED BY W. H. Walker TITLE OIL AND GAS INSPECTOR DATE MAY 24 1982

CONDITIONS OF APPROVAL, IF ANY: