	and the second sec			
Submit 3 Copies To Appropriate District	State of New	Mexico	CISÍD	Form C-103
Office			H.Y	
	Energy, Minerals and N	atural Resources,	V V	Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240 District []			WELL API NO.	
811 South First, Artesia, NM 88210	OIL CONSERVATION	ON DIVISION	30-015	
District [1]	1220 South St. Francis Dr.		5. Indicate Type of	Lease
1000 Rio Brazos Rd., Aztec, NM 87410			STATE	
District IV	Santa Fe, NM	87505		
1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & Ga	s Lease No.
87505			L-6	287
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	CES AND REPORTS ON WEL	LS		Jnit Agreement Name:
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR	PLUG BACK TO A		mit Agreement Name.
DIFFERENT RESERVOIR. USE "APPLIC	CATION FOR PERMIT" (FORM C-101)	FORSUCH		
			$\mathbf{N}$	
1. Type of Well:			2/	
Oil Well Gas Well	Other Plug & Aba	ndon (10 2002	() Irish Hills	s Yeso JE State
2. Name of Operator			8. Well No.	J LEBO OH DEALE
Yates Petroleum Corpora	ation 🦉			0
3. Address of Operator		LUCH ADICOL	C.A.L.	3
105 South Fourth Street		2	Pool name or Wil	
	- Artesia, NM 88210	Č.	<u>/Penasco</u> Draw	San Andres Yeso
4. Well Location		1018873645		
		268L3GV		
Unit Letter H :	2310 feet from the Nort		60 feet from t	he East line
				he <u>East</u> line
Section 12	Township 19S	Range 24E M		
		Cange 24E r	MPM Eddy C	ounty
	10. Elevation (Show whether			
	3596' G			
11. Check A	ppropriate Box to Indicate N	Nature of Notice, Re	port or Other Da	a
NOTICE OF INT	FINTION TO-			
			QUENT REPO	
		. REMEDIAL WORK		LTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI	NG OPNS. 🔲 🛛 PI	
	—			
TEMPORARILY ABANDON     Image: Construction       PULL OR ALTER CASING     Image: Construction		CASING TEST AND		
	—			
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB		
		CASING TEST AND CEMENT JOB OTHER:		
PULL OR ALTER CASING	MULTIPLE	CASING TEST AND CEMENT JOB OTHER:	Al	
PULL OR ALTER CASING	MULTIPLE	CASING TEST AND CEMENT JOB OTHER:	Al	
	MULTIPLE	CASING TEST AND CEMENT JOB OTHER:	Al	
PULL OR ALTER CASING DTHER: 12. Describe proposed or completed of starting any proposed work). or recompilation.	MULTIPLE  COMPLETION  d operations. (Clearly state all per SEE RULE 1103. For Multiple	CASING TEST AND CEMENT JOB OTHER: entiment details, and give Completions: Attach we	Al pertinent dates, incl ellbore diagram of p	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>12. Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a</li> </ul>	MULTIPLE	CASING TEST AND CEMENT JOB OTHER: entiment details, and give Completions: Attach we	Al pertinent dates, incl ellbore diagram of p	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>12. Describe proposed or completed of starting any proposed work).</li> <li>or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> </ul>	MULTIPLE  COMPLETION  d operations. (Clearly state all per SEE RULE 1103. For Multiple nd rigged up pulling ur	CASING TEST AND CEMENT JOB OTHER: rtinent details, and give Completions: Attach we	Al pertinent dates, incl ellbore diagram of p equipment. Sh	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>12. Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Trinent details, and give Completions: Attach we nit and plugging	Al pertinent dates, incl ellbore diagram of p equipment. Sh	ANDONMENT
PULL OR ALTER CASING DTHER: 12. Describe proposed or completed of starting any proposed work). or recompilation. 8-28-2002 - Moved in a night. 8-29-2002 - Rigged up on tubing to close wel	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: artinent details, and give Completions: Attach we nit and plugging th rods. Well c	Al pertinent dates, incl ellbore diagram of p equipment. Sh ame in on crew	ANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>12. Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit.</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: artinent details, and give Completions: Attach we nit and plugging th rods. Well c	Al pertinent dates, incl ellbore diagram of p equipment. Sh ame in on crew d down wellbes	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>12. Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Intinent details, and give Completions: Attach we nit and plugging ith rods. Well c c ell down. Nipple CIBP and set CIBP	Al pertinent dates, incl ellbore diagram of p equipment. Sh ame in on crew d down wellhea at 2526' CI	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>12. Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Intinent details, and give Completions: Attach we nit and plugging ith rods. Well c c ell down. Nipple CIBP and set CIBP	Al pertinent dates, incl ellbore diagram of p equipment. Sh ame in on crew d down wellhea at 2526' CI	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>12. Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel</li> <li>8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: artinent details, and give Completions: Attach we nit and plugging th rods. Well c all down. Nipple CIBP and set CIBP	Al pertinent dates, incl ellbore diagram of p equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>12. Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel</li> <li>8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: artinent details, and give Completions: Attach we nit and plugging th rods. Well c all down. Nipple CIBP and set CIBP b'. Rigged up ce 74'. POOH. Shu	Al pertinent dates, incl ellbore diagram of p equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in WO	BANDONMENT
PULL OR ALTER CASING DTHER: 12. Describe proposed or completed of starting any proposed work). or recompilation. 8-28-2002 - Moved in a night. 8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit. up BOP. POOH with 2-3 set. POOH with CIBP. 25 sack Class C Neat c 8-31-9-3-2002 - RIH wi	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Trinent details, and give Completions: Attach we nit and plugging ith rods. Well c ell down. Nipple CIBP and set CIBP o'. Rigged up ce 74'. POOH. Shu	Al pertinent dates, incl ellbore diagram of pa equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated bol	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH wi mud. POOH to 983'. S</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Intrinent details, and give Completions: Attach we nit and plugging ith rods. Well c ith ro	Al pertinent dates, incl ellbore diagram of particulates equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH wi mud. POOH to 983'. S</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Intrinent details, and give Completions: Attach we nit and plugging ith rods. Well c ith ro	Al pertinent dates, incl ellbore diagram of particulates equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH wi mud. POOH to 983'. S</li> <li>WOC 4 hours. RIH with</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Intrinent details, and give Completions: Attach we nit and plugging ith rods. Well c ith ro	Al pertinent dates, incl ellbore diagram of particulates equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH with mud. POOH to 983'. S</li> <li>WOC 4 hours. RIH with 983-694'. POOH. Shut</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Attinent details, and give Completions: Attach we nit and plugging th rods. Well c and set CIBP of Rigged up ce 74'. POOH. Shu ment at 2237'. C Neat cement fr Spotted 20 sack	Al pertinent dates, incl ellbore diagram of part equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel</li> <li>8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH with mud. POOH to 983'. S</li> <li>WOC 4 hours. RIH with 983-694'. POOH. Shut</li> <li>9-4-2002 - RIH with tu</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Attinent details, and give Completions: Attach we nit and plugging th rods. Well c and set CIBP of Rigged up ce 74'. POOH. Shu ement at 2237'. C Neat cement fr Spotted 20 sack at 657'. POOH a	Al pertinent dates, incl ellbore diagram of pr equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat nd laid down t	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel</li> <li>8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH with mud. POOH to 983'. S</li> <li>WOC 4 hours. RIH with 983-694'. POOH. Shut</li> <li>9-4-2002 - RIH with tu</li> <li>down BOP. RIH with tu</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: rtinent details, and give Completions: Attach we nit and plugging th rods. Well c and set CIBP o'. Rigged up ce 74'. POOH. Shu ement at 2237'. C Neat cement fr Spotted 20 sack at 657'. POOH at a 30 sacks Clas	Al pertinent dates, incl ellbore diagram of pr equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat nd laid down t s C Neat cemen	BANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH with 2-3 set.</li> <li>WOC 4 hours. RIH with 983-694'. POOH. Shut 9-4-2002 - RIH with tu down BOP. RIH with tu surface. Rigged down</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Trinent details, and give Completions: Attach we nit and plugging ith rods. Well c and set CIBP o'. Rigged up ce 74'. POOH. Shu ement at 2237'. C Neat cement fr Spotted 20 sack at 657'. POOH at a 30 sacks Class ND wellhead. Ho	Al pertinent dates, incl ellbore diagram of particular equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat nd laid down t s C Neat cemen le staved full	JANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close well</li> <li>8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH with 2-3 set.</li> <li>WOC 4 hours. RIH with 983-694'. POOH. Shut</li> <li>9-4-2002 - RIH with tu down BOP. RIH with tu surface. Rigged down</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Trinent details, and give Completions: Attach we nit and plugging ith rods. Well c ell down. Nipple CIBP and set CIBP o'. Rigged up ce 74'. POOH. Shu ement at 2237'. C Neat cement fr Spotted 20 sack at 657'. POOH a ed 30 sacks Clas ND wellhead. Ho	Al pertinent dates, incl ellbore diagram of part equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat nd laid down t s C Neat cemen le stayed full od belief Installe	JANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close well</li> <li>8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH with 2-3 set.</li> <li>WOC 4 hours. RIH with 983-694'. POOH. Shut</li> <li>9-4-2002 - RIH with tu down BOP. RIH with tu surface. Rigged down</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Trinent details, and give Completions: Attach we nit and plugging ith rods. Well c ell down. Nipple CIBP and set CIBP o'. Rigged up ce 74'. POOH. Shu ement at 2237'. C Neat cement fr Spotted 20 sack at 657'. POOH a ed 30 sacks Clas ND wellhead. Ho	Al pertinent dates, incl ellbore diagram of part equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat nd laid down t s C Neat cemen le stayed full od belief Installe	JANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DESCRIBE proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH with 983-694'. POOH. Shut</li> <li>9-4-2002 - RIH with tu down BOP. RIH with tu surface. Rigged down</li> <li>hereby certify that the information a a bandonment/marker. Provide the surface of the surfac</li></ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Antinent details, and give Completions: Attach we not and plugging th rods. Well c and set CIBP of Rigged up ce 74'. POOH. Shu ement at 2237'. C Neat cement fr Spotted 20 sack at 657'. POOH at a 30 sacks Class ND wellhead. Ho pest of my knowledge an NAL REPORT. Plu	Al pertinent dates, incl ellbore diagram of pr equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat nd laid down t s C Neat cemen le stayed full id belief.Installe gging complete	ANDONMENT uding estimated date roposed completion ut down for . Put valve d and nippled BP would not . Pumped a C. e with plugging 3'. POOH. cement from ubing. Nippled t from 421' to . Rigged down d regulation 
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close well</li> <li>8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH with 2-3 set.</li> <li>WOC 4 hours. RIH with 983-694'. POOH. Shut</li> <li>9-4-2002 - RIH with tu down BOP. RIH with tu surface. Rigged down</li> </ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Trinent details, and give Completions: Attach we nit and plugging ith rods. Well c ell down. Nipple CIBP and set CIBP o'. Rigged up ce 74'. POOH. Shu ement at 2237'. C Neat cement fr Spotted 20 sack at 657'. POOH a ed 30 sacks Clas ND wellhead. Ho	Al pertinent dates, incl ellbore diagram of pr equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat nd laid down t s C Neat cemen le stayed full id belief.Installe gging complete	ANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Antinent details, and give Completions: Attach we not and plugging th rods. Well c and set CIBP of Rigged up ce 74'. POOH. Shu ement at 2237'. C Neat cement fr Spotted 20 sack at 657'. POOH at a 30 sacks Class ND wellhead. Ho pest of my knowledge an NAL REPORT. Plu	Al pertinent dates, incl ellbore diagram of pr equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat nd laid down t s C Neat cemen le stayed full id belief.Installe gging complete	ANDONMENT uding estimated date roposed completion ut down for . Put valve d and nippled BP would not . Pumped a C. e with plugging 3'. POOH. cement from ubing. Nippled t from 421' to . Rigged down d regulation 
<ul> <li>PULL OR ALTER CASING</li> <li>DESCRIBE proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH with 983-694'. POOH. Shut</li> <li>9-4-2002 - RIH with tu down BOP. RIH with tu surface. Rigged down</li> <li>hereby certify that the information a a bandonment/marker. Provide the surface of the surfac</li></ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Antinent details, and give Completions: Attach we not and plugging th rods. Well c and set CIBP of Rigged up ce 74'. POOH. Shu ement at 2237'. C Neat cement fr Spotted 20 sack at 657'. POOH at a 30 sacks Class ND wellhead. Ho pest of my knowledge an NAL REPORT. Plu	Al pertinent dates, incl ellbore diagram of pa equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat nd laid down t s C Neat cemen le stayed full d belief.Installe gging complete CIAN DA	ANDONMENT uding estimated date roposed completion ut down for . Put valve d and nippled BP would not . Pumped a C. e with plugging 3'. POOH. cement from ubing. Nippled t from 421' to . Rigged down d regulation 
PULL OR ALTER CASING DTHER: 2. Describe proposed or completed of starting any proposed work). or recompilation. 8-28-2002 - Moved in a night. 8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit. up BOP. POOH with 2-3 set. POOH with CIBP. 25 sack Class C Neat c 8-31-9-3-2002 - RIH with mud. POOH to 983'. S WOC 4 hours. RIH with 983-694'. POOH. Shut 9-4-2002 - RIH with tu down BOP. RIH with tu surface. Rigged down hereby certify that the information a a bandonment marker. P IGNATURE	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Antinent details, and give Completions: Attach we not and plugging th rods. Well c and set CIBP of Rigged up ce 74'. POOH. Shu ement at 2237'. C Neat cement fr Spotted 20 sack at 657'. POOH at a 30 sacks Class ND wellhead. Ho pest of my knowledge an NAL REPORT. Plu	Al pertinent dates, incl ellbore diagram of pa equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat nd laid down t s C Neat cemen le stayed full d belief.Installe gging complete CIAN DA	JANDONMENT
<ul> <li>PULL OR ALTER CASING</li> <li>DTHER:</li> <li>Describe proposed or completed of starting any proposed work). or recompilation.</li> <li>8-28-2002 - Moved in a night.</li> <li>8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit.</li> <li>up BOP. POOH with 2-3 set. POOH with CIBP.</li> <li>25 sack Class C Neat c</li> <li>8-31-9-3-2002 - RIH with 1000000000000000000000000000000000000</li></ul>	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Antinent details, and give Completions: Attach we not and plugging th rods. Well c and set CIBP of Rigged up ce 74'. POOH. Shu ement at 2237'. C Neat cement fr Spotted 20 sack at 657'. POOH at a 30 sacks Class ND wellhead. Ho pest of my knowledge an NAL REPORT. Plu	Al pertinent dates, incl ellbore diagram of pa equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat nd laid down t s C Neat cemen le stayed full d belief.Installe gging complete CIAN DA	JANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Antinent details, and give Completions: Attach we not and plugging th rods. Well c and set CIBP of Rigged up ce 74'. POOH. Shu ement at 2237'. C Neat cement fr Spotted 20 sack at 657'. POOH at a 30 sacks Class ND wellhead. Ho pest of my knowledge an NAL REPORT. Plu	Al pertinent dates, incl ellbore diagram of pr equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat nd laid down t s C Neat cemen le stayed full d belief.Installe gging complete CIAN DA Telephone	ANDONMENT uding estimated date roposed completion ut down for . Put valve d and nippled BP would not . Pumped a C. e with plugging 3'. POOH. cement from ubing. Nippled t from 421' to . Rigged down d regulation . TE9-16-02 (1) No. 505-748-1471
PULL OR ALTER CASING DTHER: 2. Describe proposed or completed of starting any proposed work). or recompilation. 8-28-2002 - Moved in a night. 8-29-2002 - Rigged up on tubing to close wel 8-30-2002 - Dug pit. up BOP. POOH with 2-3 set. POOH with CIBP. 25 sack Class C Neat c 8-31-9-3-2002 - RIH with mud. POOH to 983'. S WOC 4 hours. RIH with 983-694'. POOH. Shut 9-4-2002 - RIH with tu down BOP. RIH with tu surface. Rigged down hereby certify that the information a a bandonment marker. P IGNATURE	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB OTHER: Antinent details, and give Completions: Attach we not and plugging th rods. Well c and set CIBP of Rigged up ce 74'. POOH. Shu ement at 2237'. C Neat cement fr Spotted 20 sack at 657'. POOH at a 30 sacks Class ND wellhead. Ho pest of my knowledge an NAL REPORT. Plu	Al pertinent dates, incl ellbore diagram of pr equipment. Sh ame in on crew d down wellhea at 2526'. CI ment equipment t well in. WO Circulated hol om from 983-88 s Class C Neat nd laid down t s C Neat cemen le stayed full d belief.Installe gging complete CIAN DA Telephone	JANDONMENT