STATE OF NEW MEXICO	
ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISECTIVED P. O. BOX 2088	Form C-103 Revised 10-1-78
SANTA FE, NEW MEXICO 87501 JUN 5 1980	Sa. Indicate Type of Leuse
DANO OFFICE O. C. D. ARTESIA, OFFICE	State         X         Fen           5. State Oil & Gas Lense No.         L-6287
SUNDRY NOTICES AND REPORTS ON WELLS IDO NOT USE THIS FOR FOR POPOSALS TO DELLE OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" IFORM C-101) FOR SUCH PROPOSALS.)	
I. OIL X CAS OTHER-	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation 🖌	8. Farm of Lease liame Irish Hills-Yeso HE State
3. Address of Operator 207 South 4th Street-Artesia, NM 88210	9. Well No. 4
A Location of Wall	10. Field and Pool, or Wildcat Penasco Draw SA Yeso (Assoc)
THE West LINE, SECTION 12 TOWNSHIP 195 RANGE 24E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 3603' GR	12. County Eddy
Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO:	ner Data FREPORT OF:
PERFORM REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
OTHER	perf & treat X.
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.	estimated dote of starting any proposed
TD 3100' - Ran 69 joints of $4\frac{1}{2}$ " 9.5# J-55 (3040) of casi	ng set at 3040'.
TD 3100' - Ran 69 joints of 4½" 9.5# J-55 (3040) of casi 1-Diff-fill shoe at 3040'. 6-Centralizers. Cemented w/35 Poz, 3# K-44, 3 gallons D-108, 2% D-65 TIC. PD 9:40 PM 5	ng set at 3040'. O sacks of 50-50
TD 3100' - Ran 69 joints of 4½" 9.5# J-55 (3040) of casi 1-Diff-fill shoe at 3040'. 6-Centralizers. Cemented w/35 Poz, 3# K-44, 3 gallons D-108, 2% D-65 TIC. PD 9:40 PM 5 circulated 10 sacks to surface. TD 3100'; PBTD 3040' - WIH W/Strip Gun on Wireline and p	ng set at 3040'. 0 sacks of 50-50 -12-80. Cement erforated 2732-41'
<u>TD 3100' -</u> Ran 69 joints of 4 <sup>1</sup> / <sub>2</sub> " 9.5# J-55 (3040) of casi 1-Diff-fill shoe at 3040'. 6-Centralizers. Cemented w/35 Poz, 3# K-44, 3 gallons D-108, 2% D-65 TIC. PD 9:40 PM 5 circulated 10 sacks to surface.	ng set at 3040'. 0 sacks of 50-50 -12-80. Cement erforated 2732-41' tubing, set at
TD 3100' - Ran 69 joints of 4½" 9.5# J-55 (3040) of casi 1-Diff-fill shoe at 3040'. 6-Centralizers. Cemented w/35 Poz, 3# K-44, 3 gallons D-108, 2% D-65 TIC. PD 9:40 PM 5 circulated 10 sacks to surface. TD 3100'; PBTD 3040' - WIH W/Strip Gun on Wireline and p w/10 .50" holes. WIH w/Guiberson Uni VI packer on 2-3/8" 2654' and acidized perforations w/500 gallons 15% acid. Pulled tubing and packer OOH. WIH w/Strip Gun on Wireline	ng set at 3040'. 0 sacks of 50-50 -12-80. Cement erforated 2732-41' tubing, set at Swabbed well dry. e and perforated
TD 3100' - Ran 69 joints of 4 <sup>1</sup> / <sub>2</sub> " 9.5# J-55 (3040) of casi 1-Diff-fill shoe at 3040'. 6-Centralizers. Cemented w/35 Poz, 3# K-44, 3 gallons D-108, 2% D-65 TIC. PD 9:40 PM 5 circulated 10 sacks to surface. TD 3100'; PBTD 3040' - WIH W/Strip Gun on Wireline and p w/10 .50" holes. WIH w/Guiberson Uni VI packer on 2-3/8" 2654' and acidized perforations w/500 gallons 15% acid. Pulled tubing and packer OOH. WIH w/Strip Gun on Wirelin 2517-23' w/12 .50" holes. POOH. RIH w/bridge plug, set Uni VI packer on 2-3/8" tubing set packer 2459'. Acidized	ng set at 3040'. 0 sacks of 50-50 -12-80. Cement erforated 2732-41' tubing, set at Swabbed well dry. e and perforated at 2557', Guiberson d perforations w/500
<u>TD 3100' -</u> Ran 69 joints of 4 <sup>1</sup> / <sub>2</sub> " 9.5# J-55 (3040) of casi 1-Diff-fill shoe at 3040'. 6-Centralizers. Cemented w/35 Poz, 3# K-44, 3 gallons D-108, 2% D-65 TIC. PD 9:40 PM 5 circulated 10 sacks to surface. <u>TD 3100'; PBTD 3040' -</u> WIH W/Strip Gun on Wireline and p w/10 .50" holes. WIH w/Guiberson Uni VI packer on 2-3/8" 2654' and acidized perforations w/500 gallons 15% acid. Pulled tubing and packer OOH. WIH w/Strip Gun on Wirelin 2517-23' w/12 .50" holes. POOH. RIH w/bridge plug, set Uni VI packer on 2-3/8" tubing set packer 2459'. Acidize gallons 15% acid. Swabbed well. Sand Frac'd perforations w/37884 gallons gelled 1% KCL water, 8500# 100 mesh & 600	ng set at 3040'. 0 sacks of 50-50 -12-80. Cement erforated 2732-41' tubing, set at Swabbed well dry. e and perforated at 2557', Guiberson d perforations w/500 2732-41' & 2517-23' 00# 20-40 sand.
<u>TD 3100' -</u> Ran 69 joints of 4½" 9.5# J-55 (3040) of casi 1-Diff-fill shoe at 3040'. 6-Centralizers. Cemented w/35 Poz, 3# K-44, 3 gallons D-108, 2% D-65 TIC. PD 9:40 PM 5 circulated 10 sacks to surface. <u>TD 3100'; PBTD 3040' -</u> WIH W/Strip Gun on Wireline and p w/10 .50" holes. WIH w/Guiberson Uni VI packer on 2-3/8" 2654' and acidized perforations w/500 gallons 15% acid. Pulled tubing and packer OOH. WIH w/Strip Gun on Wirelin 2517-23' w/12 .50" holes. POOH. RIH w/bridge plug, set Uni VI packer on 2-3/8" tubing set packer 2459'. Acidize gallons 15% acid. Swabbed well. Sand Frac'd perforations w/37884 gallons gelled 1% KCL water, 8500# 100 mesh & 600 WIH w/Strip Gun on wireline and perforated 2418-26 & 2369	ng set at 3040'. 0 sacks of 50-50 -12-80. Cement erforated 2732-41' tubing, set at Swabbed well dry. e and perforated at 2557', Guiberson d perforations w/500 2732-41' & 2517-23' 00# 20-40 sand. -78' as follows:
<u>TD 3100' -</u> Ran 69 joints of 4½" 9.5# J-55 (3040) of casi l-Diff-fill shoe at 3040'. 6-Centralizers. Cemented w/35 Poz, 3# K-44, 3 gallons D-108, 2% D-65 TIC. PD 9:40 PM 5 circulated 10 sacks to surface. <u>TD 3100'; PBTD 3040' -</u> WIH W/Strip Gun on Wireline and p w/10 .50" holes. WIH w/Guiberson Uni VI packer on 2-3/8" 2654' and acidized perforations w/500 gallons 15% acid. Pulled tubing and packer OOH. WIH w/Strip Gun on Wirelin 2517-23' w/12 .50" holes. POOH. RIH w/bridge plug, set Uni VI packer on 2-3/8" tubing set packer 2459'. Acidize gallons 15% acid. Swabbed well. Sand Frac'd perforations w/37884 gallons gelled 1% KCL water, 8500# 100 mesh & 600 WIH w/Strip Gun on wireline and perforated 2418-26 & 2369 2418-26 w/8 .50" holes (1 shot per foot) and 2369-78' w/8 WIH w/bridge plug, set at 2439' w/tubing and packer. Acid	ng set at 3040'. 0 sacks of 50-50 -12-80. Cement erforated 2732-41' tubing, set at Swabbed well dry. e and perforated at 2557', Guiberson d perforations w/500 2732-41' & 2517-23' 00# 20-40 sand. -78' as follows: 5.50" holes (1 spf) dized perforations
<u>TD 3100' -</u> Ran 69 joints of 4½" 9.5# J-55 (3040) of casi 1-Diff-fill shoe at 3040'. 6-Centralizers. Cemented w/35 Poz, 3# K-44, 3 gallons D-108, 2% D-65 TIC. PD 9:40 PM 5 circulated 10 sacks to surface. <u>TD 3100'; PBTD 3040' -</u> WIH W/Strip Gun on Wireline and p w/10 .50" holes. WIH w/Guiberson Uni VI packer on 2-3/8" 2654' and acidized perforations w/500 gallons 15% acid. Pulled tubing and packer OOH. WIH w/Strip Gun on Wirelin 2517-23' w/12 .50" holes. POOH. RIH w/bridge plug, set Uni VI packer on 2-3/8" tubing set packer 2459'. Acidize gallons 15% acid. Swabbed well. Sand Frac'd perforations w/37884 gallons gelled 1% KCL water, 8500# 100 mesh & 600 WIH w/Strip Gun on wireline and perforated 2418-26 & 2369 2418-26 w/8 .50" holes (1 shot per foot) and 2369-78' w/8 WIH w/bridge plug, set at 2439' w/tubing and packer. Aci w/1000 gallons 15% acid. Pulled tubing and packer. Aci w/1000 gallons 15% acid. Pulled tubing and packer. Sand w/30240 gallons gelled 1% KCL water, 15000# 100 mesh and	ng set at 3040'. 0 sacks of 50-50 -12-80. Cement erforated 2732-41' tubing, set at Swabbed well dry. e and perforated at 2557', Guiberson d perforations w/500 2732-41' & 2517-23' 00# 20-40 sand. -78' as follows: . 50" holes (1 spf) dized perforations Frac'd perforations 60000# 20-40 sd. Pull
<u>TD 3100' -</u> Ran 69 joints of 4½" 9.5# J-55 (3040) of casi l-Diff-fill shoe at 3040'. 6-Centralizers. Cemented w/35 Poz, 3# K-44, 3 gallons D-108, 2% D-65 TIC. PD 9:40 PM 5 circulated 10 sacks to surface. <u>TD 3100'; PBTD 3040' -</u> WIH W/Strip Gun on Wireline and p w/10 .50" holes. WIH w/Guiberson Uni VI packer on 2-3/8" 2654' and acidized perforations w/500 gallons 15% acid. Pulled tubing and packer OOH. WIH w/Strip Gun on Wirelin 2517-23' w/12 .50" holes. POOH. RIH w/bridge plug, set Uni VI packer on 2-3/8" tubing set packer 2459'. Acidize gallons 15% acid. Swabbed well. Sand Frac'd perforations w/37884 gallons gelled 1% KCL water, 8500# 100 mesh & 600 WIH w/Strip Gun on wireline and perforated 2418-26 & 2369 2418-26 w/8 .50" holes (1 shot per foot) and 2369-78' w/8 WIH w/bridge plug, set at 2439' w/tubing and packer. Acid	ng set at 3040'. 0 sacks of 50-50 -12-80. Cement erforated 2732-41' tubing, set at Swabbed well dry. e and perforated at 2557', Guiberson d perforations w/500 2732-41' & 2517-23' 00# 20-40 sand. -78' as follows: . 50" holes (1 spf) dized perforations Frac'd perforations 60000# 20-40 sd. Pull
<u>TD 3100' -</u> Ran 69 joints of 4½" 9.5# J-55 (3040) of casi 1-Diff-fill shoe at 3040'. 6-Centralizers. Cemented w/35 Poz, 3# K-44, 3 gallons D-108, 2% D-65 TIC. PD 9:40 PM 5 circulated 10 sacks to surface. <u>TD 3100'; PBTD 3040' -</u> WIH W/Strip Gun on Wireline and p w/10 .50" holes. WIH w/Guiberson Uni VI packer on 2-3/8" 2654' and acidized perforations w/500 gallons 15% acid. Pulled tubing and packer OOH. WIH w/Strip Gun on Wirelin 2517-23' w/12 .50" holes. POOH. RIH w/bridge plug, set Uni VI packer on 2-3/8" tubing set packer 2459'. Acidize gallons 15% acid. Swabbed well. Sand Frac'd perforations w/37884 gallons gelled 1% KCL water, 8500# 100 mesh & 600 WIH w/Strip Gun on wireline and perforated 2418-26 & 2369 2418-26 w/8 .50" holes (1 shot per foot) and 2369-78' w/8 WIH w/bridge plug, set at 2439' w/tubing and packer. Aci w/1000 gallons 15% acid. Pulled tubing and packer. Aci w/1000 gallons 15% acid. Pulled tubing and packer. Sand w/30240 gallons gelled 1% KCL water, 15000# 100 mesh and	ng set at 3040'. 0 sacks of 50-50 -12-80. Cement erforated 2732-41' tubing, set at Swabbed well dry. e and perforated at 2557', Guiberson d perforations w/500 2732-41' & 2517-23' 00# 20-40 sand. -78' as follows: . 50" holes (1 spf) dized perforations Frac'd perforations 60000# 20-40 sd. Pull
<ul> <li><u>TD 3100' -</u> Ran 69 joints of 4½" 9.5# J-55 (3040) of casi 1-Diff-fill shoe at 3040'. 6-Centralizers. Cemented w/35 Poz, 3# K-44, 3 gallons D-108, 2% D-65 TIC. PD 9:40 PM 5 circulated 10 sacks to surface.</li> <li><u>TD 3100'; PBTD 3040' -</u> WIH W/Strip Gun on Wireline and p w/10 .50" holes. WIH w/Guiberson Uni VI packer on 2-3/8" 2654' and acidized perforations w/500 gallons 15% acid. Pulled tubing and packer OOH. WIH w/Strip Gun on Wirelin 2517-23' w/12 .50" holes. POOH. RIH w/bridge plug, set Uni VI packer on 2-3/8" tubing set packer 2459'. Acidize gallons 15% acid. Swabbed well. Sand Frac'd perforations w/37884 gallons gelled 1% KCL water, 8500# 100 mesh &amp; 600 WIH w/Strip Gun on wireline and perforated 2418-26 &amp; 2369 2418-26 w/8 .50" holes (1 shot per foot) and 2369-78' w/8 WIH w/bridge plug, set at 2439' w/tubing and packer. Aci w/1000 gallons 15% acid. Pulled tubing and packer. Sand w/30240 gallons gelled 1% KCL water, 15000# 100 mesh and <u>BP OOH &amp; Complete to the best of my trowledge and belief. Instited of the best of my trowledge and b</u></li></ul>	ng set at 3040'. 0 sacks of 50-50 -12-80. Cement erforated 2732-41' tubing, set at Swabbed well dry. e and perforated at 2557', Guiberson d perforations w/500 2732-41' & 2517-23' 00# 20-40 sand. -78' as follows: . 50" holes (1 spf) dized perforations Frac'd perforations 60000# 20-40 sd. Pull