

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

C/SF

NM 30888

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR MONSANTO COMPANY	8. FARM OR LEASE NAME APEX FEDERAL
3. ADDRESS OF OPERATOR 1330 Midland NBT, Midland, Tx. 79701	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2244' FNL & 410' FEL of Sec. 3	10. FIELD AND POOL, OR WILDCAT ARTESIA QUEEN (Grayburg SA)
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 3, T-19S, R-27E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3468' Gr.	12. COUNTY OR PARISH Eddy
	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*


To Plug and abandon well.

1. Set a CIBP @ 1585' and dump 35' of cement on top of plug.
2. Circulate hole with 9 ppg mud with 25 Sx. of Gel per 100 Bbls. of mud.
3. Set a 10 Sx. Cement plug at the surface.
4. Set a 4' well marker at surface.

Work will start approximately 2/18/82

RECEIVED

FEB 19 1982

O. C. D.
ARTESIA, OFFICEOIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Regional Prod. Mgr. DATE 2/5/82

(This space for Federal or State office use)

APPROVED BY (O.C.D.) PETER W. CHESTER
CONDITIONS OF APPROVAL, IF ANY:

FEB 18 1982

FOR

JAMES A. GILHAM *See Instructions on Reverse Side
DISTRICT SUPERVISOR