

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED BY SANTA FE, NEW MEXICO 87501

MAY -8 1987

O. C. D.

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR RE-ENTER BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Chevron U.S.A. Inc.	8. Farm or Lease Name Eddy J.P. State Comm.
3. Address of Operator P.O. Box 670 Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>750</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>18S</u> RANGE <u>31E</u> N.M.P.M.	10. Field and Pool, or Wildcat Shugart Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3643.8	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to P&A subject well by PQH w/tbg and pkr. Set CIBP at 11,940', cap w/35' cement. Circ. abandonment mud (10ppg brine w/25 ppb swg). Set plugs as follows:
A. Strawn 10,990' - 10,890 (35 sx) B. Wolfcamp 10,175' - 10,075 (35 sx)
C. Top of cmt 7,950' - 7,850 (35 sx) D. Bonespring 6,750 - 6,650 (inside and outside 5 1/2" csg, must be tagged, 50sx)
E. Intermediate csg shoe - 4,635 - 4,535'
(inside and outside 5 1/2" csg must be tagged - 50 sx).
F. Base of salt, 2,440' - 2,340' (inside and outside 5 1/2" csg - 50sx)
G. Surf csg shoe 650' - 550', (inside and outside 5 1/2" csg (50sx)
H. Surf. plug. 60' - 0' (inside and outside 5 1/2" csg, (10sx)
Cut off wellhead and install dry hole marker. change status to P&A.

Notary Public, O.C.D. in full-time time to the well

Plugging

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. E. Abbin TITLE Staff Drilling Engineer DATE 5-7-87

APPROVED BY Mike Williams OIL AND GAS INSPECTOR DATE MAY 12 1987