			4
<b> </b>	State of New Mexico		Form C-103 CS
Submit 3 Copies	Energy, merals and Natural Resources Department		Revised 1-1-89
to appropriate Energy, minerals and Natural Resources Department Revised 1-1-59			$\mathcal{H}$
DISTRICT I	OIL CONSERVATION DIVISION		ELL API NO.
P.O. Box 1980, Hobbs, NM 88240	0, Hobbs, NM 88240 P.O. Box 2088		30-015-23585
DISTRICT II Santa Fe, New Mexico 87504-2088		504-2088	Indicate Type of Lease
P.O. Drawer DD, Artesia, NM 88210	0 - 12.3456		STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 37410	NM 87410		State Oil & Gas Lease No.
SUNDRY NOT	TICES AND REPORTS ON WELLS	102 mg 3	
L ( DO NOT LISE THIS FORM FOR PR	OPOSALS TO DRILL OR TO DEEPEN OF	ELOG BACK TO A	Lease Name or Unit Agreement Name
DIFFERENT RESE	RVOIR. USE "APPLICATION FOR PERMIT C-101) FOR SUCH PROPOSALS)	ARTED 3	
1. Type of Well:	- IUI) FOR SUCH PHOPOGRA		
	OTHER SWICES		Routh NU Deep Com SWD
WELL WELL	SWD CELES UVS REHTO		Well No.
2. Name of Operator V	Name of Operator // YATES PETROLEUM CORPORATION		2
3. Address of Operator		9.	Pool name or Wildcat
105 South 4th St., Ar	tesia, NM 88210		SWD - Devonian
4. Well Location			
Unit Letter <u>B</u> : <u>660</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line			
Section 14 Township 19S Range 24E NMPM Eddy County			
10. Elevation (Show whether DF, RKB, RT, GR, etc.)			
	3649'		
11. Check	Appropriate Box to Indicate Nat	ure of Notice, Repo	ort, or Other Data
NOTICE OF IN		SUBSE	
TEMPORARILY ABANDON CHANGE PLANS			
PULL OR ALTER CASING			
OTHER: Remedial Work			
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
work) SEE RULE 1103. Propose to perform Casing Integrity Test and perform remedial work as follows:			
Propose to perform casing integrity fest and perform femediat work as selections			
1. Perform Casing Integrity Test. If test is good, contact OCD-Artesia (505-748-1283)			
24 hours prior to performing Casing Integrity Test and recording on chart. If casing does			
not test, proceed as follows:			
2. Nights up BOP TOOH with packer and $3-1/2$ " plastic coated tubing.			
a TTH with workstring, packer and RBP. Set RBP at 9300' and packer at 8300'. Pressure			
up on annulus to 900 psi and wait 10 minutes to see if pressure bleeds off. If annulus			
loses pressure, may indicate a problem with the casing up hole from 8300'. Pressure up on tubing to 1200 psi to tset interval between the packer and RBP to check below packer.			
tubing to 1200 psi to	- toot interval between th	e packer and RB	P to check below packer.
	J LSEL INCEIVAL DECWEEN en		
Keen testing until 16	eaks are found.		
Keep testing until le 4. Isolate leak, est	eaks are found. tablish an injection rate	and a pressure.	TIH with RBP and cement
Keep testing until le 4. Isolate leak, est retainer Squeeze as	eaks are found. tablish an injection rate s necessary. WOC 24 hours	and a pressure. . Re-squeeze i	TIH with RBP and cement f necessary.
Keep testing until lo 4. Isolate leak, est retainer. Squeeze as 5. Drill out cement	eaks are found. tablish an injection rate s necessary. WOC 24 hours retainer and TOOH with RB	and a pressure. s. Re-squeeze i BP. TIH with tu	TIH with RBP and cement f necessary. bing, packer & RBP to pressure
Keep testing until lo 4. Isolate leak, est retainer. Squeeze as 5. Drill out cement	eaks are found. tablish an injection rate s necessary. WOC 24 hours retainer and TOOH with RB give and complete to the best of my knowledge and beli	and a pressure. s. Re-squeeze i BP. TIH with tu id. CON	TIH with RBP and cement f necessary. bing, packer & RBP to pressure TINUED ON NEXT PAGE:
Keep testing until le 4. Isolate leak, est retainer. Squeeze as 5. Drill Out cement Ihereby certify the the information above if	eaks are found. tablish an injection rate s necessary. WOC 24 hours retainer and TOOH with RB give and complete to the best of my knowledge and beli	and a pressure. s. Re-squeeze i BP. TIH with tu id. CON	TIH with RBP and cement f necessary. bing, packer & RBP to pressure TINUED ON NEXT PAGE:
Keep testing until lo 4. Isolate leak, est retainer. Squeeze as 5. Drill out cement	eaks are found. tablish an injection rate s necessary. WOC 24 hours retainer and TOOH with RB give and complete to the best of my knowledge and beli	and a pressure. s. Re-squeeze i BP. TIH with tu id. CON	TIH with RBP and cement f necessary. bing, packer & RBP to pressure TINUED ON NEXT PAGE: chnician
Keep testing until le 4. Isolate leak, est retainer. Squeeze as 5. Drill out cement I hereby certify the the information above if SKONATURE	eaks are found. tablish an injection rate s necessary. WOC 24 hours retainer and TOOH with RB me fod complete to the best of my knowledge and beli	and a pressure. s. Re-squeeze i BP. TIH with tu id. CON	TIH with RBP and cement f necessary. bing, packer & RBP to pressure TINUED ON NEXT PAGE: chnician June 30, 2000
Keep testing until lo 4. Isolate leak, est retainer. Squeeze as 5. Drill out cement Thereby certify that the information above if skonature	eaks are found. tablish an injection rate s necessary. WOC 24 hours retainer and TOOH with RB me fod complete to the best of my knowledge and beli	and a pressure. s. Re-squeeze i BP. TIH with tu id. CON	TIH with RBP and cement f necessary. bing, packer & RBP to pressure TINUED ON NEXT PAGE: chnician June 30, 2000
Keep testing until lo 4. Isolate leak, est retainer. Squeeze as 5. Drill out cement I hereby certify that the information above if skonature TYPE OR FRUNT NAME Rusty Kle	eaks are found. tablish an injection rate s necessary. WOC 24 hours retainer and TOOH with RB me fod complete to the best of my knowledge and beli	and a pressure. s. Re-squeeze i BP. TIH with tu id. CON	TIH with RBP and cement f necessary. bing, packer & RBP to pressure TINUED ON NEXT PAGE: chnician June 30, 2000
Keep testing until le 4. Isolate leak, est retainer. Squeeze as 5. Drill out cement I hereby certify the the information above if SKONATURE	eaks are found. tablish an injection rate s necessary. WOC 24 hours retainer and TOOH with RB months for the best of my knowledge and beling much for the best of my knowledge and beling in	and a pressure. Re-squeeze i P. TIH with tu id. CON Operations Tec	TIH with RBP and cement f necessary. bing, packer & RBP to pressure TTINUED ON NEXT PAGE: chnician DATE June 30, 2000 TELEPHONE NO. 505/748-1471
Keep testing until le 4. Isolate leak, est retainer. Squeeze as 5. Drill out cement I hereby certify that the information above if SKONATURE SKONATURE TYPE OR PRINT NAME Rusty Kle	eaks are found. tablish an injection rate s necessary. WOC 24 hours retainer and TOOH with RB months for the best of my knowledge and beling much for the best of my knowledge and beling in	and a pressure. Re-squeeze i P. TIH with tu id. CON Operations Tec	TIH with RBP and cement f necessary. bing, packer & RBP to pressure TINUED ON NEXT PAGE: chnician June 30, 2000
Keep testing until le 4. Isolate leak, est retainer. Squeeze as 5. Drill out cement I hereby certify that the information above if SKONATURE SKONATURE TYPE OR PRINT NAME Rusty Kle	eaks are found. tablish an injection rate s necessary. WOC 24 hours retainer and TOOH with RB months for the best of my knowledge and beling much for the best of my knowledge and beling in	and a pressure. s. Re-squeeze i BP. TIH with tu id. CON	TIH with RBP and cement f necessary. bing, packer & RBP to pressure TTINUED ON NEXT PAGE: chnician DATE June 30, 2000 TELEPHONE NO. 505/748-1471

YATES PETROLEUM CORPORATION Routh NU Deep Com #2 SWD Section 14-T19S-R24E Eddy County, New Mexico

SUNDRY NOTICE CONTINUED:

test the squeezed interval.

6. Hydrotest packer, on/off tool, profile nipple and 3-1/2" plastic coated tubing in the hole. Set packer at  $9340'\pm$ .

7. Nipple down BOP and nipple up wellhead. Load annulus with 105 bbls of packer fluid containing oxygen scavenger and biocide. Perform Mechanical Integrity Test and record on chart - 1000 psi for 10 minutes. NOTIFY OCD-ARTESIA (505-748-1283) IN SUFFICIENT TIME TO WITNESS MECHANICAL INTEGRITY TEST

8. TOOH with tools. Release well to production department to return well to injection.

Rust Klein Operations Technician June 30, 2000