

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

dist  
DP

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.

MAY 11 '90

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Sara AHA Com

1. Type of Well:  
OIL WELL  GAS WELL  OTHER RE-ENTRY

8. Well No.  
1

2. Name of Operator  
YATES PETROLEUM CORPORATION

9. Pool name or Wildcat  
South Dagger Draw Upper Penn

3. Address of Operator  
105 South 4th St., Artesia, NM 88210

4. Well Location  
Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line  
Section 11 Township 20S Range 24E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3608' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-8-90. Cleaned location. Dug out cellar. Tie onto 5 1/2" and 8-5/8" casing. ND wellhead and NU BOP. Moved in reverse unit. MIRU pulling unit.  
5-9-90. Drilled out 10' surface plug. WIH to 70'. Tag cement. Began drilling. Drilled to 870' at 7:00 AM 5-9-90.  
5-10-90. Drilled cement to 1270'. Circulate hole clean. Test casing to 1500 psi, OK. Continue drilling cement to 3273'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.  
SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 5-10-90  
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)  
ORIGINAL SIGNED BY  
APPROVED BY MIKE WILLIAMS TITLE SUPERVISOR, DISTRICT II DATE MAY 21 1990  
CONDITIONS OF APPROVAL, IF ANY: