Form 9-331 Dec. 1973 UNITED STATESDrawer DD	Form Approved. Budget Bureau No. 42-R1424
onnes onnes, soo	5. LEASE
DEPARTMENT OF THE INTERIOR IN CORD	<u>NM-8247</u>
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME RECEIVED
(Do not use this form for proposals to drill or to deepen or plug back to a different (reservoir, Use Form 9–331–C for such proposals.)	
1	8. FARM OR LEASE NAME Gulf Federal Com NOV 1.0.1000
1. oil gas ⊠ other	Gulf Federal Com NOV 1 9 1982 9. WELL NO.
2. NAME OF OPERATOR	1
Chama Petroleum Company	10 ELEL D OR WILL DOAT MANY
3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME ARTESIA, OFFICE
P.O. Box 31405, Dallas, Texas 75231	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA 3
below.)	Sec. 25-195-25E
AT SURFACE: 660' FSL & 660' FWL Sec. 35	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Eddy New Mexico
AT TOTAL DEPTH:	14. API NO.
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	3500' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
EST WATER SHUT-OFF	D) = (C) = ((V) + (V) + (V) = (V)
EPAIR WELL	(NOTE: Paper de la contraction de la contractio
ULL OR ALTER CASING	(NOTE: Report results of multiple completion or izong change on Form 9-330.)
	NOV 1 2 1982
HANGE ZONES	
	OIL & BAS
other) Drilling Activity	MINERALS MONT. SERVICE
 Drilling Activity DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dir measured and true vertical depths for all markers and zones pertinent 	EXHERALS LIGHT. SERVICE ROSWELL, NEW MEXICO rectionally drilled, give subsurface locations and t to this work.)* 00, no progress, at 3:00 ran in n. circulated hole good tools
 Drilling Activity DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dir measured and true vertical depths for all markers and zones pertinent 1-3-82: Jarred & worked tools from 9:00 till 3:0 2" upset tubing, pumped with Halliburtor 	EXHERALS LIGHT. CERVICE ROSWELL, NEW MEXICO rectionally drilled, give subsurface locations and t to this work.)* 00, no progress, at 3:00 ran in n. Circulated hole good tools
 Drilling Activity 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dir measured and true vertical depths for all markers and zones pertinent 1-3-82: Jarred & worked tools from 9:00 till 3:0 2" upset tubing, pumped with Halliburtor still would not come free, laid down 2" ubsurface Safety Valve: Manu. and Type 	EXHERALS LIGHT. SERVICE ROSWELL, NEW MEXICO rectionally drilled, give subsurface locations and to this work.)* 00, no progress, at 3:00 ran in n, circulated hole good, tools tubing.
 Drilling Activity 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dir measured and true vertical depths for all markers and zones pertinent 1-3-82: Jarred & worked tools from 9:00 till 3:0 2" upset tubing, pumped with Halliburtor still would not come free, laid down 2" 	EXHERALS LIGHT. SERVICE ROSWELL, NEW MEXICO rectionally drilled, give subsurface locations and to this work.)* 00, no progress, at 3:00 ran in n, circulated hole good, tools tubing.
 Drilling Activity DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dia measured and true vertical depths for all markers and zones pertinent 1-3-82: Jarred & worked tools from 9:00 till 3:0 2" upset tubing, pumped with Halliburtor still would not come free, laid down 2" ubsurface Safety Valve: Manu. and Type 8. Thereby certify that the foregoing is true and correct 	EXHERALS LIGHT. SERVICE ROSWELL, NEW MEXICO all pertinent details, and give pertinent dates, rectionally drilled, give subsurface locations and t to this work.)* 00, no progress, at 3:00 ran in n, circulated hole good, tools tubing. Set @Ft.
 Drilling Activity DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dia measured and true vertical depths for all markers and zones pertinent 1-3-82: Jarred & worked tools from 9:00 till 3:0 2" upset tubing, pumped with Halliburtor still would not come free, laid down 2" still would not come free, laid down 2" Subsurface Safety Valve: Manu. and Type 8. Thereby certify that the foregoing is true and correct IGNED 	EXHERALS LIGHT. SERVICE ROSWELL, NEW MEXICO rectionally drilled, give subsurface locations and to this work.)* 00, no progress, at 3:00 ran in n, circulated hole good, tools tubing. Set @Ft. <u>DATE</u> November 8, 1982
 Drilling Activity DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dim measured and true vertical depths for all markers and zones pertinent 1-3-82: Jarred & worked tools from 9:00 till 3:0 2" upset tubing, pumped with Halliburtor still would not come free, laid down 2" still would not come free, laid down 2" Subsurface Safety Valve: Manu. and Type 8. Thereby certify that the foregoing is true and correct IGNED 	EXHERALS MONT. SERVICE ROSWELL, NEW MEXICO rectionally drilled, give subsurface locations and to this work.)* 00, no progress, at 3:00 ran in n, circulated hole good, tools tubing. Set @Ft.
other) Drilling Activity 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dim measured and true vertical depths for all markers and zones pertinent 1-3-82: Jarred & worked tools from 9:00 till 3:0 2" upset tubing, pumped with Halliburtor still would not come free, laid down 2" Subsurface Safety Valve: Manu. and Type 8. I hereby certify that the foregoing is true and correct IGNED ITTLE President ACCEPTED FOR RECORD ITTLE President ORIG. SGD.) DAVID R. GLASS	BillERALS LIGHT. SERVICE ROSWELL, NEW MEXICO rectionally drilled, give subsurface locations and to this work.)* 00, no progress, at 3:00 ran in n, circulated hole good, tools tubing. Set @Ft.
 Drilling Activity DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dim measured and true vertical depths for all markers and zones pertinent 1-3-82: Jarred & worked tools from 9:00 till 3:0 2'' upset tubing, pumped with Halliburtor still would not come free, laid down 2'' still would not come free, laid down 2'' Subsurface Safety Valve: Manu. and Type 8. Thereby certify that the foregoing is true and correct IGNED Intrue President ACCEPTED FOR RECORD INTLE President IORIG. SGD.) DAVID R. GLASS 	EXHERALS LIGHT. SERVICE ROSWELL, NEW MEXICO all pertinent details, and give pertinent dates, rectionally drilled, give subsurface locations and to this work.)* 00, no progress, at 3:00 ran in n, circulated hole good, tools tubing. Set @Ft.
 Drilling Activity DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dim measured and true vertical depths for all markers and zones pertinent 1-3-82: Jarred & worked tools from 9:00 till 3:0 2" upset tubing, pumped with Halliburtor still would not come free, laid down 2" still would not come free, laid down 2" Subsurface Safety Valve: Manu. and Type I hereby certify that the foregoing is true and correct IGNED I hereby certify that the foregoing is true and correct IGNED I hereby Certify that the foregoing is true and correct IGNED I hereby Certify that the foregoing is true and correct IGNED I hereby Certify that the foregoing is true and correct IGNED I hereby Certify that the foregoing is true and correct IGNED I hereby Certify that the foregoing is true and correct IGNED I hereby Certify that the foregoing is true and correct IGNED 	BillERALS LIGHT. SERVICE ROSWELL, NEW MEXICO rectionally drilled, give subsurface locations and to this work.)* 00, no progress, at 3:00 ran in n, circulated hole good, tools tubing. Set @Ft.
 Drilling Activity 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent 1-3-82: Jarred & worked tools from 9:00 till 3:0 2'' upset tubing, pumped with Halliburtor still would not come free, laid down 2'' still would not come free, laid down 2'' Subsurface Safety Valve: Manu. and Type 8. Thereby certify that the foregoing is true and correct IGNED Markers Difference of the space for Federal or State offic (ORIG. SGD.) DAVID R. GLASS US. GEOLOGICAL SLIPVEY 	Boswell, New Mexico all pertinent details, and give pertinent dates, rectionally drilled, give subsurface locations and t to this work.)* OO, no progress, at 3:00 ran in n, circulated hole good, tools tubing. Set @Ft
 Drilling Activity 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dim measured and true vertical depths for all markers and zones pertinent 1-3-82: Jarred & worked tools from 9:00 till 3:0 2" upset tubing, pumped with Halliburtor still would not come free, laid down 2" still would not come free, laid down 2" ubsurface Safety Valve: Manu. and Type 8. Thereby certify that the foregoing is true and correct GNED GNED ACCEPTED FOR RECORD INTLE President ORIG. SGD.) DAVID R. GLASS 	Boswell, New MEXICO all pertinent details, and give pertinent dates, rectionally drilled, give subsurface locations and t to this work.)* OO, no progress, at 3:00 ran in n, circulated hole good, tools tubing. Set @Ft

•

F

.....

-