

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

ATE*
DO TO-

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

CLSF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐


2. NAME OF OPERATOR
Santa Fe Exploration Company (505/623-2733)

3. ADDRESS OF OPERATOR
P. O. Box 1136, Roswell, NM 88202-1136

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1980' FSL & 660' FWL of Section

14. PERMIT NO.

15. ELEVATIONS (Show whether BY, RT, OF, etc.)
3459.1 GL



5. LEASE DESIGNATION AND SERIAL NO.
NM-19442 ✓

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Mason Federal

9. WELL NO.
#1 ✓

10. FIELD AND POOL, OR WILDCAT
N. Hackberry (Y SR) Est.

11. SEC., T., R., M., 35 BLK. AND SURVEY OR AREA
Sec. 33, T19S, R31E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETION
ABANDON*
CHANGE PLANT

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1. Pick up tubing & SN, GIH.
2. Swab dry; if no production then
3. Load hole w/water
4. Spot 50 sx cement from 2403-2100' ✓
5. Wait until set-up then tag ✓
- * 6. Set 50' plug at surface ✓
7. Install dry hole marker

* 5a. Perf. 5 1/2" csg. at 1050'.
Cement from 0' to 1050',
both sides of csg. ✓

18. I hereby certify that the foregoing is true and correct

SIGNED

Steve L. Simmons

TITLE Steve L. Simmons, Agent

DATE 12/20/85

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

1-2-86

*See Instructions on Reverse Side