NEW MEXICO OIL CONSERVATION COMMUNITION DRAWER DD ARTESIA, NEW MEXICO

Ę,

FIELD REPORT FOR CEMENTING OF WELLS

1	SAGE E	ENERGY	Lease	ANTEL	OPE SINK	14	ell # Z	
Location of Well	Unit Section			Townsh I9	ip Ran 24	~ /	ounty EDDY	
Drilling Contractor		STERLIN	i લ .	Туре	of Equipm	^{ent} Ra	omey	
* = CS6. T		APPROV	ED CASI	ING PRO	GRAM			······································
Size of Ho	le Size	of Casing	-		New or U	sed D	epth	Sacks Cem
17'/z		12.3/4"	<u> </u>	#	BIEW	3	500'	circ
11"		3 ⁵ /8"	24		11		'GOFI	CIFC
17/8 "		41/2	10.5 € 11.6		£ 1	5	8700'	1500
Type of Sh	oe used <u>6.</u> 1800 Sa	Size of C Float c etFee O with Z	ollar u t of 85 00 sa	sed L SInch icks ne	<mark>s€.</mark> Btm 3 2 4 [#] Gra at cement	jts wo de K- around	elded <u></u> 55 d shoe	Yes
New-used c + 400	sax Hower	lite	additiv	'es 14	Clocele, 15th	<u>/sk.qil</u>	sonit	Call 21
New-used c + _400 Plug down	sax <u>Hower</u> @ [:30	(AM) (PM)	Date_	- 7/1	Clocele, 15" 5	<u>/sk. qil</u>	sonit	<u>, CaCl</u> , 21
New-used c + <u>#00</u> Plug down Cement cir Cemented b Temp. Surv	sax <u>Hower</u> @ <u>1:30</u> culated y Ho cy ran @	Aite (AM) (PM) Yes (Hiburto) (AM) (P	Date_ M) Dat	<u>7/1</u> _No. 0 _Witne .e	<u>Clocele, 15</u> 5 f Sack <u>s</u> ssed by	/sk.qil //	sonit	<u>, CaCl</u> , 21
New-used c + <u>400</u> Plug down Cement cir Cemented b Temp. Surv Casing tes Method Use	sax <u>Hower</u> [] <u>1:30</u> culated y <u>Ho</u> cy ran [] t [] d	(AM) (PM) Yes (AM) (PM) (AM) (PM) (AM) (PM)	Date () (M) Dat (M) Dat	7/1 No. 0 Witne .e Witne	Socks Sacks Ssed bytop	/sk.qil //	sonit	<u>, CaCl</u> , 21
New-used c + <u>#00</u> Plug down Cement cir Cemented b Temp. Surv Casing tes Method Used Checked fo	sax <u>Hower</u> <u>a</u> <u>1:30</u> culated y <u>Ho</u> cy ran <u>e</u> t <u>e</u> d r shut off	(AM) (PM) Yes (AM) (PM) (AM) (PM) (AM) (PM) (AM) (PM)	Date M) Dat M) Dat M) Dat	7/1 No. 0 Witne e .e Witne Date	<u>S</u> f Sack <u>s</u> ssed by top	/sk.qil //	sonit	<u>, CaCl</u> , 21
New-used c + <u>400</u> Plug down Cement cir Cemented b Temp. Surv Casing tes Method Used Checked fo Method used	sax <u>Hower</u> <u>a</u> <u>1:30</u> culated <u>y Ho</u> cy ran <u>e</u> t <u>e</u> d r shut off d	(AM) (PM) Yes (AM) (PM) (AM) (PM) (AM) (PM)	Date M) Dat M) Dat M) Dat	7/1 No. 0 Witne e Witne Date Witne	Socks Ssed by top ssed by ssed by ssed by ssed by	<u>/sk. qil</u> Da cemen	o sx	5. 100/6.5.