

CIS
JP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-015-25181
Indicate Type of Lease STATE FEE ☒
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name Anderson Com
Well No. 1
Pool name or Wildcat Dagger Draw Strawn, East

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER	
Name of Operator Nearburg Producing Company	
Address of Operator 3300 N A St., Bldg 2, Suite 120, Midland, TX 79705	
Well Location Unit Letter B 660 Feet From The North Line and 1980 Feet From The East Line Section 10 Township 20S Range 25E NMPM Eddy County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3404' GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Nearburg Producing Company requests to plug and abandon the above referenced well.

- 1.) MIRU service rig. 100' Plug 8958' to 9058' T49
- 2.) Set CIBP @ 8325' w/ 35' cmt or spot 25 sx plug.
- 3.) Load hole w/ 10# brine, w/ 25# gel per bbl.
- 4.) Spot 100' plug @ top of Wolfcamp (6305' 6210' to 6310'). And Perf CSG. squeeze 100' of cmt outside CSG 6210' to 6310'
- 5.) Cut 4-1/2" CSG @ 3,000' and pull. Perf CSG - squeeze 100' of cmt outside CSG 3900' to 4000'. Leave 100' of cmt inside CSG. 3900' to 4000'
- 6.) Spot 100' plug 50' and 50' out of stub. WOC, tag.
- 7.) Spot 100' plug 850' to 950' (Top of San Andres 922')
- 8.) Spot 100' plug 300' to 400' (Base of 13-3/8" 350')
- 9.) Set surface plug and dry hole marker.
- 10.) RDMO. 60'

Notify OCD 24 hrs. prior to any work done

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kim Stewart TITLE Regulatory Analyst DATE 09-26-01

TYPE OR PRINT NAME Kim Stewart

TELEPHONE NO. 915/686-8235

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE 10-5-01

CONDITIONS OF APPROVAL, IF ANY: