Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISIO **DISTRICT I** WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 Santa Fe, New Mexico 87504-2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 STATE DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" Bogart (FORM C-101) FOR SUCH PROPOSALS.) Type of Well: METT X OTHER 8. Well No. 2. Name of Operator #1 Nearburg Producing Company 9. Pool name or Wildcat 3. Address of Operator Atoka Glorieta - Yeso 75381-3085 P. O. Box 823085, Dallas, TX Well Location Line and 1,980South 1,980 Feet From The Feet From The Unit Letter Eddy Township 19S 26E **NMPM** Range 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,363.1 GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF NOTICE OF INTENTION TO: ALTERING CASING PERFORM REMEDIAL WORK REMEDIAL WORK PLUG AND ABANDON PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. **TEMPORARILY ABANDON CHANGE PLANS** CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. MIRU well service unit. ND wellhead and NU BOPE. Set CIBP @ 2,650'. Cap with 25 sx cement. Circ hole with 10# brine with 25# gel/bbl. Set 25 sx cement plug @ 1,500' and tag @ 1,325'. Set 30 sx cement plug @ 950'. Tag @ 740'. OCD witnessed. Set 25 sx cement plug @ 450'. Cut wellhead off. Set dry hole marker with 10 sx cement @ surface. Clean location. I hereby certify that the information 11/22/95 Drilling Supt. SIGNATURE Willis TYPE OR PRINT NAME

TILE Field Rep. II