

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL. (E)  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

45F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different str.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

AUG 15 '89

2. NAME OF OPERATOR

Harvey E. Yates Company

3. ADDRESS OF OPERATOR

P.O. Box 1933, Roswell, New Mexico 88202

O. C. D.  
ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

Unit letter O, 430' FSL & 1650' FEL

5. LEASE DESIGNATION AND SERIAL NO.

NM 2537

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

South Taylor 13 Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT  
Shugart, 7-Rivers, Queen, Grbg,  
San Andres

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 13, T18S, R31E

14. PERMIT NO.

30-015-257411

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3727.4 GL

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8-1-89 POH w/rods & pump. POH w/TBG. Set RBP @ 4150'.

8-2-89 Correlate abrasa jet tool & set @ 3792. Abrasa Jet 2 cuts @ 3792 & acidize w/1000 gals 10% MSR-100. Swab to test.

8-4-89 Frac cuts @ 3792 w/7800 gals 30# X-link & 3000# 12-20 Ottawa.

8-6-89 Hang well on pump. SN @ 3857. Anchor @ 3407.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Manager/Engineer

DATE 8-10-89

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side