

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87504

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED
DEC 28 '88
O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4222
7. Unit Agreement Name
8. Farm or Lease Name JMD State
9. Well No. 2
10. Field and Pool, or Wildcat Und. W. Millman-GR
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER- ☐

Name of Operator
Morexco, Inc.

Address of Operator
P. O. Box 481, Artesia, NM 88210

Location of Well
UNIT LETTER L 1650 FEET FROM THE South LINE AND 330 FEET FROM
West 12 LINE, SECTION 19S TOWNSHIP 27E RANGE 27E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3272' Grd.

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-13-88 T. D. well at 1820'. Run logs.
12-14-88 Run logs, lay down pipe and release rig.
12-17-88 Rig up unit and swab test open hole.
12-19-88 Circulate hole with 10# brine w/25#/bbl. salt gel. Spot 35 sx. plug from 1690'-1590'. Tag top of plug at 1570'. Spot 35 sx. plug from 1330'-1230'. Tag top of plug at 1220'. Spot 35 sx. plug from 365'-265'. Tag top of plug at 250'. Set 10' sx. surface plug. Will install marker, clean location and cover pits.

Post ID-2
2-3-89
P4A

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Becky Olson TITLE Agent DATE 12-28-88
APPROVED BY Danell Moore TITLE Geologist DATE 4/10/89