|  |   |   |   | 1 .   |
|--|---|---|---|---|
|  |   |   | RECLIVED  | CIST  |
| Form 3160-5<br>(June 1990)   | UNITED ST<br>DEPARTMENT OF T<br>BUREAU OF LAND M  | HE INTERIOR   | OCT 2 9 1991<br>O. C. D.  | FORM APPROVED<br>Budget Bureau No. 1004-0135<br>Expires: March 31, 1993<br>5. Lease Designation and Serial No.<br>NGC-029388-B                        |
| Do not use this fo<br>U:   | SUNDRY NOTICES AND R<br>rm for proposals to drill or to<br>se "APPLICATION FOR PERM   | deepen or reentry to                                | LS<br>a different reservoir.  | 6. If Indian, Allottee or Tribe Name  |
| SUBMIT IN TRIPLICATE   |   |   |   | 7. If Unit or CA. Agreement Designation   |
| I. Type of Well     Gas       Well     Gas       Well     Other  |   |   |   | 8. Well Name and No.<br>A.J. "11"Federal No.1<br>9. API Well No.  |
| Marathon Oil<br>3. Address and Telephone N<br>P. O. Box 55   | •<br>2 Midland, Tx. 91  | 5-682-1626  |   | 10. Field and Pool, or Exploratory Area<br>Tamano (Bone Spring)   |
| 4 Location of Well (Footage, Sec. T. R. M. or Survey Description)<br>Unit P, 560' FSL & 990" FEL<br>Section 11, T-18-S, R-31-E, NMPM |   |   |   | 11. County or Parish, State<br>Eddy County, N.M.  |
| CHECK A  | APPROPRIATE BOX(s) TO I   | NDICATE NATURE                                      | OF NOTICE, REPO   | RT, OR OTHER DATA   |
| TYPE OF S  | TYPE OF SUBMISSION TYPE OF ACTI   |   |   |   |
| Notice of  | f Intent  | Abandonment<br>Recompletion<br>Plugging Back        |   | Change of Plans  Change of Plans  New Construction  Non-Routine Fracturing  |
| Final Ab   | andonment Notice  | Casing Repair Altering Casing Other                 |   | Water Shut-Off  Water Shut-Off  Dispose Water  (Note: Report results of multipl: completion on Well Completion or Recompletion Report and Log Jurn of |
| give subsurface loca<br>Marathon Oil<br>No. 1 to a w<br>when the uni   | tions and measured and true vertical deputs<br>vater injection well.<br>It becomes effective or<br>ject water into the Tam<br>ed is the NMOCD Form No<br>ocedure: | conversion of t<br>This well will<br>January 1, 199 | he Harvey E. Yato<br>be renamed the Ta<br>2. Approval has<br>g) Pool by Order | been granted by the<br>No. R-9555 attached.   |
| XPT  | Toval<br>Aoregoing is true and correct  | dry <sub>ide</sub> _Northwest                       | Production Supt.  | Date 1215-91  |
| (This space for Federal  | or State office use   |   | - 440 J - 127   | Date  |

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent or or representations as to any matter within its jurisdiction.

Form 3160-5 A. J. "11" Federal No. 1

- 1. MIRU PU. POOH laying down rods and pump.
- 2. Nipple down well head & nipple up BOP.
- 3. Release TAC and POOH laying down 2 3/8" production string.
- 4. RU wireline unit and set RBP at 8025', dumpbailing 2 sxs sand on plug. Set cement retainer at 7920'.
- 5. PU 2 7/8" workstring. RIH w/stinger and sting into cement retainer. Establish injection rate w/fresh water.
- 6. Squeeze Shingle zone perfs 8005' to 8024' w/100 sxs of Class H w/6/10% fluid loss and 50 sxs Class H w/2#/sx salt.
- 7. Sting out of cement retainer, reverse clean & POOH.
- 8. RIH w/bit and collars on workstring. Drill out retainer & cement. Test squeeze to 500 psi.
- 9. POOH w/collars and bit.
- 10. RIH w/retrieving head on workstring. Circulate sand off plug. Retrieve plug & POOH.
- RU perforators and perforate Second Bone Spring 2 JSPF from 8121' to 11. 8197'. RD perforators.
- 12. PU 5 1/2" RITS tool, seating nipple and RIH on workstring. Set packer 8000'.
- Acidize Second Bone Spring Carbonate perfs 8005' to 8197' w/2000 gals 13. of 15% HCL acid.
- 14. Swab back load.
- 15. Unset packer. POOH laying down workstring and packer.
- 16. Pick up a wireline re-entry guide (IPC & EPC), 2 3/8" x 5 1/2" Baker Lok-Set (EPC and internally lined w/fiberglas) or equivalent, on-off tool (EPC and w/1.50 316 stainless steel profile) on 2 3/8" internally fiberglass lined injection tubing. Set packer at 7950'.
- Release on-off tool and reverse circulate 2% KCL w/1 bbl packer fluid 17. down backside (est. 116 bbls). Latch onto on-off tool.
- 18. Nipple down BOP and nipple up well head.
- 19. Conduct mechanics integrity test on backside for one hour.
- 20. RDMO PU.
- 21. Connect well to injection system and commence injection into Second Bone Spring Carbonate.
- After approximately two weeks of injection, RU loggers and conduct 22. injection profile survey.

This work is scheduled during the month of January, 1911.