

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

+ d51
up

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

MAR 16 1993

WELL API NO. 30-015-26412
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-689
7. Lease Name or Unit Agreement Name SST
8. Well No. #4
9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUGBACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PLUGBACK" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Harvey E. Yates Company	
3. Address of Operator P.O. Box 1933, Roswell, N.M. 88202	
4. Well Location Unit Letter <u>F</u> : <u>1697</u> Feet From The <u>West</u> Line and <u>2030</u> Feet From The <u>North</u> Line Section <u>6</u> Township <u>19S</u> Range <u>29E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3386.7' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <u>Temp plugback & test Grayburg & SA</u> <input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set temp RBP @ 3100' above sqz holes @ 3302'
- 2) Perf & test San Andres @ approx 2600'; Acdz & test
- 3) Perf & test Grayburg @ approx 2100'; Acdz & test
- 4) Possibly test San Andres @ 2570'; Poss acdz & frac

NOTE: If not commercial then sqz off, drl out & pull RBP. Put Bone Spring back on production. If commercial, set CIBP @ 6525 & 30' cmt form perm. plugback.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ray F. Nokes TITLE Prod Mgr/Eng. DATE 3/8/93
TELEPHONE NO. _____
TYPE OR PRINT NAME _____

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____

CONDITIONS OF APPROVAL, IF ANY:

DATE _____

MAR 19 1993

2025 RELEASE UNDER E.O. 14176