

OIL CONSERVATION DIVISION

DISTRICT I  
P. O. Box 1980 Hobbs, NM 88240

P. O. Box 2088  
Santa Fe, New Mexico 87504-2088

DISTRICT II  
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd, Aztec, NM 87410

Well API NO.	30-015-26412
5. Indicate Type or Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	V-689
7. Lease Name or Unit Agreement Name	SST
8. Well No.	#4
9. Pool name or Wildcat	MILLMAN QUEEN GB-SA, EAST

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> WELL WELL OTHER	2. Name of Operator Harvey E. Yates Company	3. Address of Operator P.O. Box 1933, Roswell, NM 88202 1-505-623-6601
4. Well Location Unit Letter F : 1,697 Feet From The WEST Line and 2,030 Feet From T NORTH Line Section 6 Township 19S Range 29E NMPM EDDY County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3386.7' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103

CURRENT PERFS: SAN ANDRES 2570-76'  
GIH w/ CIBP & SET @ 2525' PLUS 35' CMT.  
PULL TO 1900' & SPOT 100' PLUG FROM 1900 TO 1800' 25' MIN PLUG.  
POOH w/ TBG. CUT 5 1/2" CSG @ 1150' & PULL. (TOC @ 1350'). \* Cut & Pull 5 1/2" CSG @ 1250'.  
GIH w TBG TO 1250' & SPOT 35 SK PLUG. (100' INSIDE & ACROSS STUB). TAG \* 35' cement plug 1300' 1150' 104'  
PULL TO 400' AND SPOT 150' PLUG (400 TO 250') 25' MIN PLUG.  
SPOT 10 SK SURFACE PLUG.  
INSTALL DRYHOLE MARKER

CUT OFF ANCHORS AND BACKFILL WORKPIT  
BRINE GEL BETWEEN PLUGS  
CALL OCD II 24 HOURS PRIOR TO COMMENCEMENT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ray F. Nokes TITLE PROD. MGR. / ENGINEER. Date 4/7/98  
TYPE OR PRINT NAME RAY F. NOKES TELEPHONE NO. 1-505-623-6601

(This space for State use)

Approved by Mrs. Smithfield Title Field Rep. H Date May 1 - 98  
Conditions of approval, if any: