

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-26605
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Pincushion AHN
8. Well No. 2
9. Pool name or Wildcat Dagger Draw Upper Penn, North
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3596' GR

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐  
2. Name of Operator  
YATES PETROLEUM CORPORATION ✓  
3. Address of Operator  
105 South 4th St., Artesia, NM 88210

4. Well Location  
Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line  
Section 25 Township 19S Range 24E NMMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: Add perforations <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to add perforations in the Canyon as follows:

- TOOH with pump. Nipple up BOP and TOOH with tubing.
- Perforate 7636-7688' (Canyon) with 14 holes (1 SPF) as follows: 7636-7640', 7646-7648', 7678, 80, 82, 84, 86 & 7688'.
- Straddle perforations 7678-7688' and acidize with 2000 gallons 20% NEFE HCL acid & ball sealers.
- Straddle perforations 7636-7648' and acidize with 2000 gallons 20% NEFE HCL acid & ball sealers.
- Straddle perforations 7636-7688' and swab test.
- Pull RBP and put well on pump.

RECEIVED

AUG 08 1995

OIL CON. DIV.  
DIST. 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE Aug. 7, 1995  
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM  
DISTRICT II SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE AUG 10 1995

CONDITIONS OF APPROVAL, IF ANY: