

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

SHACKELFORD OIL CO.

3a. Address

P.O. Box 10665 Midland, TX

3b. Phone No. (include area code)

915-682-9784

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FNL + 2310' FNL

Sec. 14 T19S R31E

5. Lease Serial No.

NM 86554

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

ARRINGTON FEO #1

9. API Well No.

30015267560051

10. Field and Pool, or Exploratory Area

SHAGART YSR, Q

11. County or Parish, State

EDDY County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☒ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Propose Temporearily ABANDON well with the following procedures:

- 1) Set CIBP 50' above perforations
- 2) Set 35 ft. cement plug on CIBP
- 3) load hole AND pressure test to 500 psi. for 30 minutes.

We plan to do this work AS SOON AS permitt is Approved AND equipment is Available.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

DON SHACKELFORD

Title Owner

Signature

[Signature]

Date

February 5, 2002

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Appro-
Condi
certify
which

Accepted for record

only

FEB 13 2002

ARA

ice does not warrant or
hts in the subject lease

Title *[Signature]*

Office

CFO

Date

2/8/2002