

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAR 23 1993

WELL API NO. 3001526980
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K6395
7. Lease Name or Unit Agreement Name Dee State
8. Well No. 6
9. Pool name or Wildcat N. Dagger Draw Upper Penn
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3598' GI

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Conoco, Inc.	3. Address of Operator 10. Dista Dr. Ste 100W, Midland, TX 79705
4. Well Location Unit Letter I 1830 Feet From The South Line and 890 Feet From The East West Line Section 36 Township 19S Range 24E NMPM Eddy County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3598' GI	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to add perfs and stimulate the Dee State No. 6 as follows:

1. RIH and perf from 7808-7830' w/4 JSPF (88 holes).
2. Acidize perfs (7782-7830') w/2000 gals 20% NeFe HCl acid and 500 gals heated 20% NeFe HCl acid.
3. Acidize perfs (7718-7770') w/3500 gals 20% NeFe HCl acid and 500 gals heated 20% NeFe HCl acid.
4. Return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Hoover TITLE Sr. Conservation Coordinator DATE 3/22/93
TYPE OR PRINT NAME Jerry W. Hoover (915) 686-6548 TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS

APR 5 1993

APPROVED BY SUPERVISOR, DISTRICT II TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: