-				3 1111000	c s
			N.M. Oil Cum	S. DIVISIU	
			811 S. 1st Stre		FORM APPROVED
rm 3160-5		ED STATES	Artesia, NM de	3210-2834	Budget Bureau No. 1004-0135
ine 1990)	DEPARTMENT	OF THE INTERIOR		1	Expires: March 31, 1993 case Designation and Serial No.
	BUREAU OF LA	AND MANAGEMENT			NM-82902
	SUNDRY NOTICES	ND REPORTS ON	WELLS		f Indian, Allottee or Tribe Name
Do not use this fo U	orm for proposals to drill ise "APPLICATION FOR	or to deepen or reen	try to a different res		
	SUBMIT		1	7. 1	f Unit or CA, Agreement Designation
Type of Well			JUY		/ell Name and No.
X Well Gat	Other		-Or RECENSON	4	omino AOJ Federal #2
. Name of Operator		(505	74840490		PI Well No.
	LEUM CORPORATION		SIA		30-015-28179
Address and Telephone h	no. th St., Artesia, N	м 88210	s i	10.	Field and Pool, or Exploratory Area
105 SOULII 41	ge, Sec., T., R., M., or Survey De	cription)	0010115131		igart-Yates-SR-Q-GB
330' FSL & 2	210' FEL of Section	on 8-T19S-R31E (U	Jnit O, SWSE)	11.	County or Parish, State
JJ0 100 0 4					
					Eddy Co., NM
CHECK	APPROPRIATE BOX) TO INDICATE NA	TURE OF NOTICE	, REPORT, (OR OTHER DATA
	I		TYPE OF		
	SUBMISSION			r	Change of Plans
Notice	of Intent	L] Abando		۲ ۲	New Construction
			•	Ī	Non-Routine Fracturing
X Subsequ	uent Report		ng Back Repair	Ī	Water Shut-Off
Π			g Casing	[Conversion to Injection
L] Final A	Abandonment Notice	X Other	Temporary Aband	lon	Dispose Water
				Ċ	Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form (
	ompleted Operations (Clearly state al	pertinent details, and give pertin	ent dates, including estimated (date of starting any	proposed work. If well is directionally drille
 Describe Proposed or Control 	options and measured and true vertic	a ucputs for an markers and co			
give subsurface loc		1			
give subsurface loc 7-18-19-99	- Moved in and rig OOH with rods and OO psi and recorde	tubing. Till W1t	h CIBP and set	CIBP at 2 ED - 7-19-	2570'. Pressured 99. FINAL REPORT.
give subsurface loc 7-18-19-99	- Moved in and rig	tubing. Till W1t	h CIBP and set	CIBP at 2 ED - 7-19-	570'. Pressured 99. FINAL REPORT.
give subsurface loc 7-18-19-99 7-20-99 - T(casing to 60	- Moved in and rig OOH with rods and OO psi and recorde anicial Integrity	tubing. Till wit d on chart. <u>TEM</u> Test performed o	on 7-19-99 and set		570'. Pressured 99. FINAL REPORT. by Gene Hunt with
give subsurface loc 7-18-19-99 7-20-99 - T(casing to 60 NOTE: Mech	- Moved in and rig OOH with rods and OO psi and recorde anicial Integrity	tubing. Till wit d on chart. <u>TEM</u> Test performed o	on 7-19-99 and set	witnessed	<u></u>
give subsurface loc 7-18-19-99 7-20-99 - T(casing to 60 NOTE: Mech	- Moved in and rig OOH with rods and OO psi and recorde anicial Integrity	tubing. Till wit d on chart. <u>TEM</u> Test performed o	on 7-19-99 and set	witnessed	by Gene Hunt with
give subsurface loc 7-18-19-99 7-20-99 - T(casing to 60 NOTE: Mech	- Moved in and rig OOH with rods and OO psi and recorde anicial Integrity	tubing. Till wit d on chart. <u>TEM</u> Test performed o	APPROVED FC	witnessed	by Gene Hunt with
give subsurface loc 7-18-19-99 7-20-99 - T(casing to 60 NOTE: Mech	- Moved in and rig OOH with rods and OO psi and recorde anicial Integrity	tubing. Till wit d on chart. <u>TEM</u> Test performed o	APPROVED FC	witnessed	by Gene Hunt with
give subsurface loc 7-18-19-99 7-20-99 - T(casing to 60 NOTE: Mech	- Moved in and rig OOH with rods and OO psi and recorde anicial Integrity	tubing. Till wit d on chart. <u>TEM</u> Test performed o	on 7-19-99 and set	witnessed	by Gene Hunt with
give subsurface loc 7-18-19-99 7-20-99 - T(casing to 60 NOTE: Mech	- Moved in and rig OOH with rods and OO psi and recorde anicial Integrity	tubing. Till wit d on chart. <u>TEM</u> Test performed o	APPROVED FC	witnessed	by Gene Hunt with
give subsurface loc 7-18-19-99 7-20-99 - T(casing to 60 NOTE: Mech	- Moved in and rig OOH with rods and OO psi and recorde anicial Integrity	tubing. Till wit d on chart. <u>TEM</u> Test performed o	APPROVED FC	witnessed	by Gene Hunt with
give subsurface loc 7-18-19-99 7-20-99 - T(casing to 60 NOTE: Mech	- Moved in and rig OOH with rods and OO psi and recorde anicial Integrity	tubing. Till wit d on chart. <u>TEM</u> Test performed o	APPROVED FC	witnessed	by Gene Hunt with
give subsurface loc 7-18-19-99 7-20-99 - To casing to 60 NOTE: Mech BLM-Carlsba	- Moved in and rig OOH with rods and OO psi and recorde anicial Integrity	tubing. TiH wit d on chart. <u>TEM</u> Test performed c hart.	APPROVED FC	witnessed	by Gene Hunt with
give subsurface loc 7-18-19-99 7-20-99 - To casing to 60 NOTE: Mech BLM-Carlsba 14. I hereby certify that d Signed	- Moved in and rig OOH with rods and OO psi and recorde anicial Integrity d. See attached of he foregoing is und correct	Test performed chart.	APPROVED FC FNDING <u>4</u>	witnessed	by Gene Hunt with
give subsurface loc 7-18-19-99 7-20-99 - To casing to 60 NOTE: Mech BLM-Carlsba 14. I hereby certify that the Signed (This space for control	- Moved in and rig OOH with rods and OO psi and recorde anicial Integrity d. See attached of the foregoing is up and correct	Test performed chart.	APPROVED FC	witnessed	by Gene Hunt with
give subsurface loc 7-18-19-99 7-20-99 - To casing to 60 NOTE: Mech BLM-Carlsba 14. I hereby certify that the Signed	- Moved in and rig OOH with rods and OO psi and recorde anicial Integrity d. See attached of the foregoing is up and correct	tubing. Till wit d on chart. <u>TEM</u> Test performed c hart. <u>hart.</u> <u>Tille_Opera</u>	APPROVED FC FNDING <u>4</u>	witnessed	by Gene Hunt with MONTH PERIO July 23, 1999 JUL 27 1999

· <u>-</u> .

