

# WELLBORE DIAGRAM

## PARKWAY DELAWARE UNIT #508

LEASE: PDU  
 LOCATION: 1360' FSL & 2620' FEL  
 FIELD: PARKWAY  
 STATUS: WATER INJ.

WELL NO. 508  
 SEC: 35 T: 19S R: 29E  
 GL: 3328' CT/ST: EDDY,NM  
 KB: DF:

API # : 30-015-30029  
 SPUD: 1/01/98  
 COMP: 1/98  
 INITIAL FORM: DELAWARE "C"

### WELL HISTORY

1/29-30/98 Run GR/CBL/CCL and Perforate  
 Acidized w/ 2600g 15% HCl  
 dropping 150 BS's throughout  
 Avg. 5.5 BPM @ 250-3000 psi  
 balled out with 106 balls  
 Ran Pkr & Fiberlined Injection Tubing  
 Initial Rate :~300 BWPD @ 300 psi  
 8/18/98 Ran injection profile survey  
 12/15/98 Acidize w/ 1000g 15%HCl  
 2/17/99 Acidize w/ 1600g 15%HCl  
 7/16/99 Acidize w/ 1000g 15%HCl  
 7/29/99 Repair tbg leak - did not find hole  
 Layed down and replaced inserts  
 8/3/99 Hydrotest in - ok.  
 5/14-15/01 Cardinal Surveys Injection Profile & SI Temp.  
 11/01 Repair tbg leak, clean out fill 4240-4310'  
 \*Recovered ~8' x 2" piece of 4 1/2" csg\*

