

NEW MEXICO
OIL CONSERVATION COMMISSION

FIELD TRIP REPORT

DATE 1-20-75

Name of Employee Leon Bergstrom

Time of Departure _____ Time of Return _____

Miles Travelled _____

In the space below please indicate purpose of trip and duties performed, listing wells or leases visited.

An inspection of four Burgett wells #1, 2, 3 & 7 in W $\frac{1}{2}$ SE $\frac{1}{4}$ Sec. 15-21-27, Eddy County, N. M. revealed the following information. Two barricades across south entrance road to this lease had been quite recently installed and was posted with a No Trespassing sign. An alternate access via Southern Union Pipeline right away from the north was used.


Burgett Pure State #1, an incomplete pumping unit was on this well which was capped with a 6" x 2" swedged nipple and 2" plug atop swedged nipple.

Burgett Pure State #2, an incomplete pumping unit was on this well which had a polished rod hanging thru a stuffing box atop 3" tubing.

Burgett Pure State #3, had a bucket placed upside down over casing with cross ties atop bucket. No pumping unit.

Burgett Pure State #7, had at least 1 joint of 1 $\frac{1}{2}$ " tubing sticking out of casing 2 or 3 ft., no pumping equipment on this well.

Some minor road repair work appeared to have been done quite recently, mostly between #2, #7 & #3.



Employee's Signature

District #II