

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, New Mexico

SUBMIT IN TRIPLICATE*
(Other instructions
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-063567

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Yates Federal

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

McMillan 7-Rivers Queen

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 6, T-20S, R-27E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

JUN 18 1984

O. C. D.
ARTESIA, OFFICE



1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW

2. NAME OF OPERATOR

Yates Energy Corporation

3. ADDRESS OF OPERATOR

Sunwest Centre, Suite 919, Roswell, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below)

At surface

990' FSL & 330' FEL

14. PERMIT

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3371' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANT ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

Revised request for approval to Plug to

(NOTE: Report results of multiple completion on Well Abandon
Completion or Recompletion Report and Log form)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6/11/84 TD 784'; 7" at 422' with 50 sxs cement. Water sands 50' to 60'; Water sands 320' to 335'. Top Seven Rivers 554'; top Queen 738'.
We plan to spot 200' plug 322' to 522'. Feel of top of plug. If not in place, respot and feel again. Displace with brine or mud. Leave brine or mud to surface. Perforate 7" casing at approximately 200' and circulate cement.
Place regulation 4" pipe dry hole marker at surface.

Look for cement in back logs of 7" TD down, circulate for 24 hrs
John

18. I hereby certify that the foregoing is true and correct

SIGNED *John R. McMinn*

TITLE John R. McMinn, Engineer

DATE June 11, 1984

(This space for Federal or State office use)

APPROVED BY *P. E.*

TITLE P.E.

DATE 6/11/84

CONDITIONS OF APPROVAL, IF ANY.

*See Instructions on Reverse Side

RECEIVED BY
JUN 13 1984
O. C. D.
ARTESIA, OFFICE

RECEIVED
JUN 14 1984
O. C. D.
HOBBY OFFICE