Operato Well Unit	Turner Federal #13	- - _ <u> </u>	TOPS
Unit API#		* Contact * Salt ge of gel g plug. * Install d * Plugs a * Plugs a * Shoe a shoe of * Surface * Where placed in the c	ct OCD 24 hrs. prior to any work done. If mud consisting of 10# brine with 25# ber barrel must be placed between each dry hole marker as per Rule 202.B.2 are to be set from point indicated up. must not be less than 100' or 25 Sacks ent, whichever is greater, unless cally indicated. and stub plugs will be 50' above and below ar stub and tagged. a plug will be from 0' - 60' plugs are required, cement must be inside and outside of all casing string(s) correct footage or sacks required, if no at exists.
7" = 745'	- Phy 745 Tog OH 847	* Plugs t	o be tagged will be indicated.

to