Gas MMGT. Operator ٦ TOPS Well <u>2c</u> Range 28 Unit Twnship 14 Section 5-02398 API # 30-0 ~ 45e' valade Base Selt ~ 6501 JOITOS + 60' Surface Plug. Contact OCD 24 hrs. prior to any work done. Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug. Install dry hole marker as per Rule 202.B.2 Plugs are to be set from point indicated up. Plugs must not be less than 100' or 25 Sacks of cement, whichever is greater, unless specifically indicated. Shoe and stub plugs will be 50' above and below shoe or stub and tagged. Surface plug will be from 0' - 60' Where plugs are required, cement must be placed inside and outside of all casing string(s) in the correct footage or sacks required, if no cement exists. Plugs to be tagged will be indicated. No Casing Records. + 450 Cement Plug Inside + Outside Casing. Top Salt Plug. TAL Procedure May Change . + Cement Plug from TD-1650 .- Shoe Plug / DASE SALT Plug . TAG Į.