

- Construction

sreitet sit 3501 erdetse i 190 al Prro, setta

The SMORE

into to the second to the adapted - and a silbord, 1, in their and the local and the seconding to the second of a the second is sell is on your state a factors. - 2000

i noisibne even fine of in or in in the bar sendition one is is well even the second of a fine to be with the interior of each one of the second of a significant interior is second of the isother in the line and this is second of tores of to.

it and the set of the structure and another the second for the sublimities of the state of the second of a structure place the of the solid the second of the second of a structure of the surgery work could be used, and a struct of the your coercosity

Tores of an inclusion first of the top of your estates

Part wirt god

.

allo .....



November 9, 1934

Mr. H. C. Wells 3501 Pershing Drive El Paso, Texas

Dear Sir:

This is in regard to the Sullivan-Rundle Well No. 1, in the NW SW, Sec. 19, T. 20 S., R. 30 E. According to the records of the State Land Office this well is on your state lease No. B-2230.

I am informed that this well is in bad condition and it is very possible that water is leaking through it into the adjacent potash bearing formations. Obviously this is a serious situation if true and one that should be remedied if at all possible.

It may be that arrangements could be made for the pulling of the pipe at this well and the proper plugging of the well for the salvage value of the pipe. If such an arrangement can be made, would it meet with your approval?

Please let me hear from you in this matter at your early convenience.

Very truly yours,

EHW:F

E. H. Wells, State Geologist.