District OIL CONSERVATION DIVISION FO. Box 2088 WELLARINO. Diffection FO. Box 2088 Santa Fe. New Moxico 87504-2088 Diffection Santa Fe. New Moxico 87504-2088 Diffection Santa Fe. New Moxico 87504-2088 Diffection Support Diffection <t< th=""><th>Submit 3 Copies</th><th>State of New Mexico Energy, Minerals and Natural Resources Depa</th><th>Form C-103 Revised 1-1-89</th></t<>	Submit 3 Copies	State of New Mexico Energy, Minerals and Natural Resources Depa	Form C-103 Revised 1-1-89
Santa Fe, New Maxico 87504-2038 5. Indices Type & Law Different Factor Santa Fe, New Maxico 87504-2038 Different Factor Support SUPPORT Support	District Office	OIL CONSERVATION DIVIS	SION WELL API NO.
CONTRACT NOTICES AND REPORTS ON WELLS IDD NOTUSE THE ROME NOR ARCONSALS: CONTRACTOR THE ROME OF ALL SALE NAME & USA APREMANT NUMBER (CHARLES TRESERVOR, USE XAPLICATION OF LIDE BACK TO A DEFERENT RESERVOR. USE XAPLICATION OF LIDE BACK DATE AND A DEFERENT RESERVOR. USE XAPLICATION OF LIDE BACK DATE AND A DEFERENT RESERVOR. USE XAPLICATION OF LIDE BACK TO A DEFERENT RESERVOR. USE XAPLICATION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: REMEDIAL WORK PLUG AND ABANDON CHANGE ACCOMPLEX DYNER AND ABANDON CONTENT AND ABANDON CHANGE PLUG AND ABANDON CHANGE PLUG AND ABANDON CHANGE PLUG AND ABANDON CHANGE ALL CONTENT AND ABANDON CONTENT AND ABANDON CHANGE PLUG AND ABANDON CHANGE ALL ABANDON CHANGE PLUG AND ABANDON CHANGE ALL CONTENT AND ABANDON CHANGE ALL ABANDON CHANGE ALL ABANDON CHANGE ALL ABANDON CHA	N.S. P. CT. I	Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease STATE FEE X
(DO NOT USE THIS FORM FOR PROPOSALS TO DAILL ON ID DEFERENT THE PROPOSALS TO DAILL ON ID DEFERENT RESERVORT. USE APPLICATION FOR PERMITY Interesting the proposal of the proposa	DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410		6. State Oil & Gas Lease No.
1. Type of Wall Average Morris & Roover 25. Nume of Opencor 8. Weil No. 1 3. Access of Opencor 8. Weil No. 1 4. Access of Opencor 8. Weil No. 1 5. O. Box 10536 Carlsbad, NM 86221-1655 Barber 4. Wall Lease 5. Ped Samuer Weiden Barber 5. Weil Case 10. Escuence (Second 20) Fees From The	(DO NOT USE THIS FORM FOR PR	OPOSALS TO DRILL OR TO DEEPEN OR PLUS BA	CK TO A 7. Lease Name or Unit Agreement Name
7. Nume of Openior Barber 011, Inc. S. WellNo. 1 Barber 011, Inc. S. WellNo. 1 Barber 011, Inc. S. Post many of Widdel Barber S. Post many of Widdel Barber S. Post many of Widdel Will Acture 0 Openior D. Box 1058 Unit Letter E: 1980 Feet From The	1. Type of Well: Of W		. Morris & Hoover
1 Access of Openior 2. 0. Box 1658 Carlsbad, NM 88221-1658 Dather 1 Will Leaton Barber Line and 660 Fee From The	2. Name of Operator		1
1 Will Lear E 1980 Feet From The North Line and 660 Feet From The West Line Section 20 Township 20 South Ramee 30 East MTM Eddy County 10: Elevisitie (Mow Vieture OF, RAD, RJ, (R, Re, e) 3240 (top of casing) 3240 (top of casing) County 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULD AN ADAMNON INTENT INC. PULL OR ALTER CASING OTHER: COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT INC. 12. Describe Proposed or Completed Operations (Clearly state all periode deails, and give periods data, including emmand data of staning any proposed work) sEE MULE 1003. Drilled to 13.1 and lost circulation. Pumped brine and paper into hole. Gasing at 40°. Drilled to 13.3 and lost circulation again. 9 (add cade rithers. Got partial return for a short trime. 19/20/39. Degrad and with clay. water gel and cader if for . Got partial return for a short trime. 10.0'. to 45'. Dril cader for . 19/21/93. Haliburt	3. Acciress of Operator	arlsbad, NM 88221-1658	
Section 20 Tomeship 20 South Rame 30 East MMM Eddy County 10 Elevation (Stave worked DF, RAB, RT, GR, etc.) 3240' (top of casing) 3240' (top of casing) 3240' (top of casing) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUESEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT IS FULL OR ALTER CASING OTHER: Attended to result of the start of the sta	4. Well Location	30 Feet From The North Line a	nd <u>660</u> Feet From The <u>West</u> Line
time. Lost circulation again. 9/20/93 - Pumped mud in pit into hole and got no returns. 9/21/93 - Haliburton pumped 25 sax cement from 100' to 45'. Let set and started pumping cement again. Lost all cement at 45'. Poured 5 yards of Ready Mix cement in the hole. 9/22/93 - checked cement at 40' (gained 5' overnight). Poured clay, water gel and fiber into hole with no success. Got permission from 0CD to plug 7" casing at 25' and cemented pipt to the surface. Set marker and cleaned location. All work directed by Eddy Potash, c/o Bob Kirby (505) 887-2844. Thereby certify that the information tooke is the and complete to the ber of my knowledge and belief. Signature Michael D. Garringer Inte President 11/8/93 THE OR PRINT NAME Michael D. Garringer Date 11/8/93 ORIGINAL STORY TRANSFERTION DATE STORY ENGINE	11. Check NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Opwork) SEE RULE 1103. 9/14/93 - ran 30' of 9/15/93 - Began drill	3240' (top of casin Appropriate Box to Indicate Nature of ITENTION TO: PLUG AND ABANDON REMEDIAL CHANGE PLANS COMMENT CASING T OTHER: erations (Clearly state all periment details, and give perime ?" casing and set in hole. Cement ing thru cement and entered old &	Ast MMM Edd) GR, etc.) GR, etc.) Motice, Report, or Other Data SUESEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. PLUG AND ABANDONMENT X TEST AND CEMENT JOB Attempt to reenter and replug Attempt to reenter and replug X end dates, including estimated date of starting any proposed nted with 35 sax. 8-5/8" casing at 40'. Drilled to to hole.
SIGNATURE	time. Lost circulati 9/20/93 - Pumped mud 9/2i/93 - Haliburton cement again. Lost a 9/22/93 - checked cem into hole with no suc pip t to the surface.	on again. in pit into hole and got no return pumped 25 sax cement from 100' to all cement at 45'. Poured 5 yard ment at 40' (gained 5' overnight) ccess. Got permission from OCD to Set marker and cleaned location	rns. o 45'. Let set and started pumping s of Ready Mix cement in the hole. . Poured clay, water gel and fiber o plug 7" casing at 25' and cemented
SIGNATURE		N I / / /	11/8/03
This space for State Use) ORIGINAL STORVET BY FOR SHITH THE AND GAS INSPECTOR DATE	SIGNATURE		505 887-2566
	(Thus space for State Use) ORIGINAL S'OF		NO GAS INSPECTOR DATE