omn 3160-5 November 1983) Formerly 9-331)	DEPAR	TME OF						ND SEL	
	BUR	EAU OF LAND	MANAGEMENT	Г	1	N	<u>M-05110-</u>		
			D REPORTS (	DN WELLS mack to a different reserve	oi <b>r</b> .	6. IF INDI	AN, ALLOTTEE	C TEIB	E NAME
OIL GAB WELL WELL				CCEIVED		7. UNIT AG	BREMENT NAM	E	
NAME OF OPERATOR		/		ALC 2 8 19	97	8. PARM 01	R LEASE NAME		
Yates Dril		pany 🖌		da . P.			<u> </u>		
ADDRESS OF OPERATO					4 *	9. WBLL N	o.	<u>a</u>	
LOCATION OF WELL (	4th Stree	et, Artesia	, NM 88210	<u>0</u>		2			
See also space 17 be At surface	low.)		ccordance with any	State requirements.*		10. FIELD	AND POOL, OR	WILDCAT	<b>r</b>
1650' FNL	& 990' FI	EL			-	11. SHC., T.	an-Seven ., e., m., or el: "By or area	<u>Rive</u> K. and	<u>ers-Q</u> N
PERMIT NO.			vs (Show whether Dr.			12-20S-	-26E		
		IS. SLEVATION	3333' GL	RT, GR, etc.)		12. COUNTY	OR PARISH	13. STA	16
		· · ·				<u>Eddy</u>		NM	
			ox To Indicate N	ature of Notice, Rep	ort, or Ot <mark>l</mark>	her Data			
	NOTICE OF INT					T REPORT	0 <b>r</b> :		
TEST WATER SHUT-C	orr	PULL OR ALTER	CASING	WATER SHUT-OFF		:	BEPAIRING WE	LL [	_
FRACTURE TREAT		MULTIPLE COMP		FRACTURE TREATM	ENT		ALTERING CAR	1-	
SHOOT CH ACIDIZH		ABANDON*		SHOOTING OR ACID	IZING		ABANDONMENT	X	
and and a second		CHANGE PLANS		(Other)	rt reunite of	multinia	completion on		
7 <del>-</del> 193 RUI	PU. Pull	ed rods and	d tubing.	details, and give pertion ons and measured and tr	ent dates, in rue vertical (	on seport cluding est depths for	and Log form timated date ( all markers a	) of startind gone	ing any 8 perti-
<ul> <li>DESCRIBE PROPOSED 0 proposed work. If nent to this work.)</li> <li>7-193 RUI</li> <li>7-293 Rai 50 whe cer</li> </ul>	PU. Pull n tubing, sxs. Cla en tagged ment. Le	ed rods and tagged at uss "C" 2% d L. Raised t et set for t	d tubing. 605'. Pull- cement. Let tubing to 560 two hours. 7	ed up to collar set for two ho 0'. Pumped 50 Fagged at 369'. ed filling casi	at 590 sxs. Cl.	'. Pun uld not ass "C'	and Log form timated date of all markers a nped tell ' 3%	) of startind some	ing any s perti-
DESCRIBE PROPOSED O proposed work. H nent to this work.) 7-193 RUI 7-293 Ran 50 whe cen to	PU. Pull n tubing, sxs. Cla en tagged ment. Le surface.	ed rods and tagged at ass "C" 2% d . Raised t et set for t Pulled tub	d tubing. 605'. Pull cement. Let tubing to 56 two hours. ' bing, finish	ed up to collar set for two ho 0'. Pumped 50 Tagged at 369'.	at 590 at 590 at 50 sxs. Cla Circu ng from	' Pun uld not ass "C' lated c surfac	and Log form timated date of all markers a nped tell ' 3%	) of startind gone	ing any s perti-
<ul> <li>DESCRIBE PROPOSED of proposed work. If nent to this work.)</li> <li>7-193 RUI</li> <li>7-293 Ration 50 where to the second second</li></ul>	PU. Pull n tubing, sxs. Cla en tagged ment. Le surface.	ed rods and tagged at ass "C" 2% d . Raised t et set for t Pulled tub	d tubing. 605'. Pull cement. Let tubing to 56 two hours. ' bing, finish	details, and give pertin- ons and measured and un set for two ho O'. Pumped 50 Tagged at 369'. ed filling casi	at 590 at 590 at 50 sxs. Cla Circu ng from	' Pun uld not ass "C' lated c surfac	and Log form timated date of all markers a nped tell ' 3%	of startind gone	ing any 8 perti-
7-1-93 RUI 7-2-93 Rat 50 whe	PU. Pull n tubing, sxs. Cla en tagged ment. Le surface.	ed rods and tagged at ass "C" 2% d . Raised t et set for t Pulled tub	d tubing. 605'. Pull cement. Let tubing to 56 two hours. ' bing, finish	details, and give pertin- ons and measured and un set for two ho O'. Pumped 50 Tagged at 369'. ed filling casi	at 590 at 590 at 50 sxs. Cla Circu ng from	' Pun uld not ass "C' lated c surfac	and Log form timated date of all markers a nped tell ' 3%	of startind sone	ing any 8 perti-
7-1-93 RUI 7-2-93 Rat 50 whe	PU. Pull n tubing, sxs. Cla en tagged ment. Le surface.	ed rods and tagged at ass "C" 2% d . Raised t et set for t Pulled tub	d tubing. 605'. Pull cement. Let tubing to 56 two hours. ' bing, finish	details, and give pertin- ons and measured and un set for two ho O'. Pumped 50 Tagged at 369'. ed filling casi	at 590 at 590 at 50 sxs. Cla Circu ng from	' Pun uld not ass "C' lated c surfac	and Log form timated date of all markers a nped tell ' 3%	of startind zone	ing any 8 perti-
<ul> <li>DESCRIBE PROPOSED of proposed work. If nent to this work.)</li> <li>7-193 RUI</li> <li>7-293 Ration 50 where to the second second</li></ul>	PU. Pull n tubing, sxs. Cla en tagged ment. Le surface.	ed rods and tagged at ass "C" 2% d . Raised t et set for t Pulled tub	d tubing. 605'. Pull cement. Let tubing to 56 two hours. ' bing, finish	details, and give pertin- ons and measured and un set for two ho O'. Pumped 50 Tagged at 369'. ed filling casi	at 590 at 590 at 50 sxs. Cla Circu ng from	' Pun uld not ass "C' lated c surfac	and Log form timated date of all markers a nped tell ' 3%	of startind sone	ing any 8 perti-
<ul> <li>DESCRIBE PROPOSED of proposed work. If nent to this work.)</li> <li>7-193 RUI</li> <li>7-293 Ration</li> <li>50 when to the second secon</li></ul>	PU. Pull n tubing, sxs. Cla en tagged ment. Le surface.	ed rods and tagged at ass "C" 2% d . Raised t et set for t Pulled tub	d tubing. 605'. Pull cement. Let tubing to 56 two hours. ' bing, finish	details, and give pertin- ons and measured and un set for two ho O'. Pumped 50 Tagged at 369'. ed filling casi	at 590 at 590 at 50 sxs. Cla Circu ng from	' Pun uld not ass "C' lated c surfac	and Log form timated date of all markers a nped tell ' 3%	of startind gone	ing any 8 perti-
<ul> <li>DESCRIBE PROPOSED 0 proposed work. Hence to this work.)</li> <li>7-193 RUI</li> <li>7-293 Rate 50 where to the second seco</li></ul>	PU. Pull n tubing, sxs. Cla en tagged ment. Le surface.	ed rods and tagged at ass "C" 2% d . Raised t et set for t Pulled tub	d tubing. 605'. Pull cement. Let tubing to 56 two hours. ' bing, finish	details, and give pertin- ons and measured and un set for two ho O'. Pumped 50 Tagged at 369'. ed filling casi	at 590 at 590 at 50 sxs. Cla Circu ng from	' Pun uld not ass "C' lated c surfac	and Log form timated date of all markers a nped tell ' 3%	of startind gone	ing any 8 perti-
<ul> <li>DESCRIBE PROPOSED of proposed work. If nent to this work.)</li> <li>7-193 RUI</li> <li>7-293 Ration 50 where to the second second</li></ul>	PU. Pull n tubing, sxs. Cla en tagged ment. Le surface.	ed rods and tagged at ass "C" 2% d . Raised t et set for t Pulled tub	d tubing. 605'. Pull cement. Let tubing to 56 two hours. ' bing, finish	details, and give pertin- ons and measured and un set for two ho O'. Pumped 50 Tagged at 369'. ed filling casi	at 590 at 590 at 50 sxs. Cla Circu ng from	' Pun uld not ass "C' lated c surfac	and Log form timated date of all markers a nped t tell ' 3%	of startind zone	ing any 8 perti-
DESCRIBE PROPOSED o proposed work, H nent to this work.) 7-193 RUI 7-293 Ran 50 whe cer to Wit	PU. Pull n tubing, sxs. Cla en tagged nent. Le surface. tnessed b	ed rods and tagged at ass "C" 2% d Raised t Pulled tul by Gene Hunt	d tubing. 605'. Pull- cement. Let tubing to 56 two hours. ' bing, finish t, Bureau of	details, and give pertin- ons and measured and un set for two ho O'. Pumped 50 Tagged at 369'. ed filling casi	at 590 at 590 at 50 sxs. Cla Circu ng from	' Pun uld not ass "C' lated c surfac	and Log form timated date of all markers a nped t tell ' 3%	of startind gone	ing any 8 perti-
DESCRIBE PROPOSED of proposed work. If nent to this work.) 7-193 RUI 7-293 Ran 50 whe cer to Wit Unit I hereby certify that SIGNED	PU. Pull n tubing, sxs. Cla en tagged nent. Le surface. tnessed b	ed rods and tagged at ass "C" 2% of Raised for f Pulled tul by Gene Hunt to Gene Hunt	d tubing. 605'. Pull cement. Let tubing to 560 two hours. ' bing, finish t, Bureau of	details, and give pertin- ons and measured and un set for two ho O'. Pumped 50 Tagged at 369'. ed filling casi	at 590 ours. Con sxs. Cl. Circul ng from t, Carls	' Pun uld not ass "C' lated c surfac	and Log form timated date of all markers a nped t tell ' 3%	) of starti nd sone	ing any s perti-
DESCRIBE PROPOSED O proposed work. If nent to this work.) 7-193 RUI 7-293 Ran 50 whe cer to Wit I bereby certify that SIGNED	PU. Pull n tubing, sxs. Cla en tagged nent. Le surface. tnessed b	ed rods and tagged at ass "C" 2% of Raised for f Pulled tul by Gene Hunt to Gene Hunt	d tubing. 605'. Pull- cement. Let tubing to 56 two hours. ' bing, finish t, Bureau of	details, and give pertin- uns and measured and un set for two ho O'. Pumped 50 Fagged at 369'. ed filling casi Land Managemen	at 590 ours. Con sxs. Cl. Circul ng from t, Carls	". Pun uld not ass "C' lated c surfac sbad.	and Log form timated date of all markers a tell ' 3% cement ce.	) of starti nd sone	ing any s perti-
beschule proposed work. H nent to this work.) 7-193 RUI 7-293 Ran 50 whe cer to Wit	PU. Pull n tubing, sxs. Cla en tagged nent. Le surface. tnessed b the foregoing the foregoing	ed rods and tagged at iss "C" 2% of Raised to Pulled tul by Gene Hunt dy Gene Hunt	d tubing. 605'. Pull- cement. Let tubing to 56 two hours. ' bing, finish t, Bureau of	details, and give pertin- uns and measured and un set for two ho O'. Pumped 50 Fagged at 369'. ed filling casi Land Managemen	at 590 ours. Con sxs. Cl. Circul ng from t, Carls	". Pun uld not ass "C' lated c surfac sbad.	and Log form timated date of all markers a tell ' 3% cement ce.	) of starti nd sone	ing any s perti-

Form 3160-5

Title 15 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.