

NO. OF COPIES RECEIVED	5	
DISTRIBUTION		
SANTA FE	1	
FILE	1-	
U.S.G.S.		
LAND OFFICE		
OPERATOR	3	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-9657

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name	
2. Name of Operator J. C. WILLIAMSON ✓	8. Farm or Lease Name U. S. Smelting State	
3. Address of Operator c/o GEO. KINGREA, 802 V&J TOWER, MIDLAND, TEXAS 79701	9. Well No. 1	
4. Location of Well UNIT LETTER G 1960.8 FEET FROM THE NORTH LINE AND 1991.9 FEET FROM THE EAST LINE, SECTION 2 TOWNSHIP 20-S RANGE 28-E NMPM.	10. Field and Pool, or Wildcat Undesignated	
15. Elevation (Show whether DF, RT, GR, etc.) 3274.9' Gr.	12. County Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 9689' LIME & SHALE  
PBD 4050' (Casing Slotted @ 3816') Top Cement 2840'  
13 3/8" set at 350' W/175 sx  
9 5/8" set at 2139' W/1275 Sx  
5 1/2" set at 9540' W/190 sx.  
Set 25 sx plug at 3816'. Cut 5 1/2" casing at 2840', pull and recover pipe. Set 25 sx. plug at 2840', 25 sx. plug at 2140' (bottom of 9 5/8") and set 10 sx. plug in surface.  
Clean location and set marker according to the New Mexico Oil Conservation Commission Rules & Regulations.

RECEIVED

AUG 11 1966

O. C. E.  
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>Geo. Kingrea</u>	TITLE <u>Prod. Engineer</u>	DATE <u>August 9, 1966</u>
APPROVED BY <u>W. A. Gressett</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>AUG 23 1966</u>
CONDITIONS OF APPROVAL, IF ANY:		