| Form 9-331 (May 1963) | | | SUBMIT IN TR | ons on re- Dudget Bur | eau Nc. 4 |
|---|---|--|---|---|---|
| | | MENT OF THE INTE GEOLOGICAL SURVEY | CRIOR verse side) | 5. LEASE DESIGNATIO | N AND SER |
| | | | | 0-12209 6. IF INDIAN, ALLOTT | EE OR TRU |
| | | ICES AND REPORT | | | |
| | Use "APPLICA | als to drill or to deepen or pl TION FOR PERMIT—" for su | ug back to a different reser ch proposals.) | roir. | |
| 1. OIL [V] GAS | | · · · · · · · · · · · · · · · · · · · | | 7. UNIT AGREEMENT I | AME . |
| WELL WELL OTHER 2. NAME OF OPERATOR (1) | | | | | |
| 2. NAME OF OPERATOR Mobil Oil Corporation | | | | 8. FARM OR LEASE NA | |
| 3. ADDEESS OF OPERA | | | ····· | Federal "V" 9. WELL NO. | Unit |
| P. 0. Box | 633, Midland | l. Texas 79701 | | A | 2 전 19 년 - 19 19 년 - 19 19 년 |
| 4. LOCATION OF WELL See also space 17 | (Report location cl | early and in accordance with | any State requirements.* | 10. FIELD AND POOL, | OR WILDC. |
| At surface | | | | Zindia | 1. (m |
| 1980' FNL, | 2310' FWL, | Unit F, Section 1 | 0, T-21-S, R-24-H | 11. SEC., T., R., M., OR SURVEY OR ARE | BLK. AND |
| | | | | संस्थित वि | - |
| 14. PERMIT NO. | | 15. ELEVATIONS (Show whethe | er DF, RT, GR, etc.) | Sec. 10, T 12. COUNTY OR PARIS | |
| | | 3942 | | Eddy | |
| 16. | | | | | New |
| | | propriate Box To Indicate | e Nature of Notice, Re | port, or Other Data | 1 |
| | NOTICE OF INTEN | TION TO : | | SUBSEQUENT REPORT OF: | |
| TEST WATER SHU | т-оғғ р | ULL OR ALTER CASING | WATER SHUT-OFF | BEPAIRING | WELL |
| FRACTURE TREAT | | IULTIPLE COMPLETE | FRACTURE TREAT | ALTERING | ASING |
| SHOOT OR ACIDIZE | | BANDON* | SHOOTING OR ACI | DIZING ABANDONMI | INT* |
| REPAIR WELL (Other) | L c | HANGE PLANS | (Other)(NOTE: Rep | wort_results of multiple completion | on Well |
| | | | Completion | or Recompletion Report and Log for | orm.) |
| Finish pul sx of Neet cement est cement, est | ling and lay cement 7677 . top of plu t. top of pl | ing $4\frac{1}{2}$ " casing, raise -7577, then pulled 2-3 og 6200, pulled 2-3 og @ 4700, pull tu | an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho | to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 34 sx of | te of star s and zor tted 2 of Nee sx Ne Neet |
| Finish pul sx of Neet cement est cement, est cement, est 10 sx plug | ling and lay cement 7677 . top of plu t. top of pl t. top of pl from 25' to | ing $4\frac{1}{2}$ " casing, ra -7577, then pulled g 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu | an 2-3/8" tbg. OF d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W | to 7677. Howco spotted 35 sx 00, Howco spotted 35 | tte of star s and zor tted 2 of Nee sx Ne Neet spott |
| Finish pul sx of Neet cement est cement, est cement, est 10 sx plug | ling and lay cement 7677 . top of plu t. top of pl t. top of pl from 25' to | ing $4\frac{1}{2}$ " casing, ra -7577, then pulled g 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install | an 2-3/8" tbg. OF d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W | to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 34 sx of wellhead equipment. | tte of star s and zor tted 2 of Nee Sx Ne Neet spott |
| Finish pul sx of Neet cement est cement, est cement, est 10 sx plug | ling and lay cement 7677 . top of plu t. top of pl t. top of pl from 25' to | ing $4\frac{1}{2}$ " casing, ra -7577, then pulled g 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install | an 2-3/8" tbg. OF d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m | tted 2 of Nee sx Ne spott . 5-22 |
| Finish pul sx of Neet cement est cement, est cement, est 10 sx plug | ling and lay cement 7677 . top of plu t. top of pl t. top of pl from 25' to | ing $4\frac{1}{2}$ " casing, ra -7577, then pulled g 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install | an 2-3/8" tbg. OF d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m | tted 2 of Nee sx Ne spott . 5-22 |
| Finish pul sx of Neet cement est cement, est cement, est 10 sx plug | ling and lay cement 7677 . top of plu t. top of pl t. top of pl from 25' to | ing $4\frac{1}{2}$ " casing, ra -7577, then pulled g 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install ervice unit @ 6:00 | an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W O p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m | tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est cement, est 10 sx plug | ling and lay cement 7677 . top of plu t. top of pl t. top of pl from 25' to | ing $4\frac{1}{2}$ " casing, ra -7577, then pulled g 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install | an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W O p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m | tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est cement, est 10 sx plug | ling and lay cement 7677 . top of plu t. top of pl t. top of pl from 25' to | ing $4\frac{1}{2}$ " casing, ra -7577, then pulled g 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install ervice unit @ 6:00 | an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W O p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m | tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est cement, est 10 sx plug | ling and lay cement 7677 . top of plu t. top of pl t. top of pl from 25' to | ing $4\frac{1}{2}$ " casing, ra -7577, then pulled g 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install ervice unit @ 6:00 | an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W O p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m | tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est cement, est 10 sx plug | ling and lay cement 7677 . top of plu t. top of pl t. top of pl from 25' to | ing $4\frac{1}{2}$ " casing, ra -7577, then pulled g 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install ervice unit @ 6:00 | an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W O p.m. 5-22-66. | to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 34 sx of wellhead equipment. | tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est cement, est 10 sx plug | ling and lay cement 7677 . top of plu t. top of pl t. top of pl from 25' to | ing $4\frac{1}{2}$ " casing, ra -7577, then pulled g 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install ervice unit @ 6:00 | an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W O p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m | tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est cement, est 10 sx plug | ling and lay cement 7677 . top of plu t. top of pl t. top of pl from 25' to | ing $4\frac{1}{2}$ " casing, ra -7577, then pulled g 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install ervice unit @ 6:00 | an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W O p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m | tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est cement, est 10 sx plug | ling and lay cement 7677 . top of plu t. top of pl t. top of pl from 25' to | ing $4\frac{1}{2}$ " casing, ra -7577, then pulled g 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install ervice unit @ 6:00 | an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W O p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m | tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est l0 sx plug Released X | ling and lay cement 7677 . top of plu t. top of pl from 25' to -Pert Well S | ring 4½" casing, ra -7577, then pulled ag 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install ervice unit @ 6:00 RECEIV | an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W O p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m | tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est cement, est 10 sx plug | ling and lay cement 7677 . top of plu t. top of pl from 25' to -Pert Well S | ring 4½" casing, ra -7577, then pulled ag 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install ervice unit @ 6:00 RECEIV | inent details, and give perti- locations and measured and an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W D p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m | tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est l0 sx plug Released X | ling and lay cement 7677 . top of plu t. top of pl from 25' to -Pert Well S | ring 4½" casing, ra -7577, then pulled ag 6200, pulled 2-3 ug @ 4700, pull tu ug @ 3200, pull tu surface, install ervice unit @ 6:00 RECEIV CTPOT | an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W O p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m Comparison of the second second second second to the second second second second second to the second se | tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est 10 sx plug Released X. | Iing and lay cement 7677 top of plu t. top of pl from 25' to -Pert Well S | ring 4½" casing, ra -7577, then pulled 2.3 ug @ 4700, pulled 2.3 ug @ 3200, pull tu surface, install ervice unit @ 6:00 RECEIV CTPOT | inent details, and give perti- locations and measured and an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W D p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m | tt of star s and zor tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est 10 sx plug Released X. | Iing and lay cement 7677 top of plu t. top of pl from 25' to -Pert Well S | ring 4½" casing, ra -7577, then pulled 2.3 ug @ 200, pulled 2-3 ug @ 3200, pull tu surface, install ervice unit @ 6:00 RECEIV CTPOTT true and correct TITLE e use) | inent details, and give perti- locations and measured and an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W D p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m P & A @ 4:00 p.m DATE 8-11 | tt of star s and zor tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est 10 sx plug Released X. | Iing and lay cement 7677 top of plu t. top of pl from 25' to -Pert Well S | ring 4½" casing, ra -7577, then pulled ag 6200, pulled 2-3 aug @ 4700, pull tu aug @ 3200, pull tu surface, install ervice unit @ 6:00 RECEIV CTDOTA true and correct <u>rue TITLE</u> s use) TITLE | inent details, and give perti- locations and measured and an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W D p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m | tt of star s and zor tted 2 of Neet spott . 5-22 |
| Finish pul sx of Neet cement est cement, est 10 sx plug Released X. 18. I hereby certify th SIGNED | Ing and lay cement 7677 top of plu t. top of pl from 25' to -Pert Well S Pert Well S Meral or State office A top A to the A | ring 4½" casing, ra -7577, then pulled ag 6200, pulled 2-3 aug @ 4700, pull tu aug @ 3200, pull tu surface, install ervice unit @ 6:00 RECEIV CTDOTA true and correct <u>rue TITLE</u> s use) TITLE | inent details, and give perti- locations and measured and an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W D p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m P & A @ 4:00 p.m DATE 8-11 | tt of star s and zon tted 2 of Neet spott . 5-22 . And the source of the source of the spott . 5-22 . And the source of the source of the sour |
| Finish pul sx of Neet cement est cement, est 10 sx plug Released X. 18. I hereby certify th SIGNED | ling and lay cement 7677 . top of plu t. top of pl from 25' to -Pert Well S Pert Well S | ring 4½" casing, ra -7577, then pulled ag 6200, pulled 2-3 aug @ 4700, pull tu aug @ 3200, pull tu surface, install ervice unit @ 6:00 RECEIV CTDOTA true and correct <u>rue TITLE</u> s use) TITLE | inent details, and give perti- locations and measured and an 2-3/8" tbg. OE d tbg. to 6300. 3/8" tubing to 48 ubing to 3300, Ho ubing, remove all state marker. W D p.m. 5-22-66. | nent dates, including estimated da true vertical depths for all marke to 7677. Howco spo Howco spotted 35 sx 00, Howco spotted 35 wco spotted 34 sx of wellhead equipment, ell P & A @ 4:00 p.m P & A @ 4:00 p.m DATE 8-11 | tt of star s and zon tted 2 of Nee sx Ne spott . 5-22 . An a solution of solution . Solution of solution of solution . Solution of solution of solution of solution . Solution of soluti |