(November (Formerly	9-5 1983) 9-331) 121			STATES THE INTERI D MANAGEMENT	OR verse alde)	5. LI	1 ofm approved. Budget Bureau No. Expires August 31. EASE DESIGNATION AND NM-12828	1985 67
	SUND	Tor prop	TICES AND	to deepen or plug b ERMIT—" for such pr	DN WELLS ack to a different reservoir. pposals.)	<u>6.</u> 1F	' INDIAN, ALLOTTRE ON	TRIBE NAME
1. OfL WELL	GAB · WELL	OTHER		<u> </u>	RECEIVED BY	7. 01	NIT AGREEMENT NAME	
2. NAME O	F OPERATOR				MAR 10 1986		IEN OR LEASE NAME	
		xas Pe	trøleum Co	orporation/			helby Federal	
3. ADDRESS	S OF OPERATOR			- 500 Md 41	O. C. D.		DLL NO.	
I. LOCATIO	N OF WELL (Repo	ort location		ccordance with any			D. 1 HIBLD AND POOL, OR WI	LDCAT
See also At surf	space 17 below.) ace	I					Kittrick Hill	
	2310' FN	IL & 990)' FEL, Se	ction 13			BEC., T., B., M., OR BLK. SURVEY OR AREA c.13, T-22-S, 1	K24E
14. PERMIT	NO.	<u> </u>		NS (Show whether DF,	RT, GB, etc.)		Eddy	New Mexico
16.				x To Indicate N	ature of Notice, Report,	or Other [Data	
	NOT	ICE OF INTE	NTION TO:	[]	8	UBSEQUENT RE	PORT OF:	
	ATER SHUT-OFF		PULL OR ALTER	11	WATER BHUT-OFF		REPAIRING WELL	·]]
	OR ACIDIZS		MULTIPLE COMP ABANDON*	X	FRACTUBE TREATMENT Shooting or acidizin		ALTERING CASIN	°
REPAIR			CHANGE PLANS		(Other)		ABANDON MENT [®]	
		لسمسا						
propo	E PROPOSED OR CO	MPLETED OP 11 is directi	ERATIONS (Clear ionally drilled, g	ly state all pertinent ive subsurface locati	(Nors: Report	completion B	tiple completion on V eport and Log form.) ing estimated date of as for all markers and	atasting and
The sub other e casing	ject well conomic re lby Federa to 10,508	is dep: complet 1 #1 ha (TOC= {	leted in i tion possi as 13-3/8" 3440 by CB	ts present p bilities, so casing to 3 SL). It also	(NoTE: Report) Completion or R	ecompletion B dates, includi vertical depth Strawn an lug and a ng to 350 s at 10,2	ing estimated date of as for all markers and abandon the w 06' and 4-1/2 330' and 10,0	starting any i sones perti- has no e11.
The sub other e The She casing Present	ject well conomic re by Federa to 10,508 open perf use the f MIRUSU an Set a CIE Set a CIE Cut the 4 plug at 8 Spot a 15 Spot a 10 Spot a 10	is dep: complet 1 #1 ha (TOC= { foration followin d wire: p @ 940 -1/2" d 325'. 0' plus 0' plus	leted in i tion possi as 13-3/8" 3440 by CB as are 946 ag procedu line. Call 00' and du 50' and du casing at g 7650-750 g 5650-550 g 3550-345	ts present p bilities, so casing to 3 bL). It also 7'-78' (Atok are to plugan BLM in Carl mp 35' cemer ± 8400'. Spo 0 at the top 0 at the top	(Nor: Report Completion or R details, and give pertinent ors and measured and true producing zones (S we propose to pl 55', 8-5/8" casin has bridge plugs a) and 9094-9100 and abandon this we sbad: 1-505-887-6 at on top to sepan at on top to sepan at a 150' cement p of the Wolfcamp of the 2nd Bone shoe of the 8-5/	ecompletion B dates, includi vertical depth Strawn and a ing to 350 s at 10,3 (Strawn) ell: 5544. tate the blug 8475 Spring s (8" casin	Atoka and St Strawn. 5'-8325'. Tag and. aband. abandon the w of and 4-1/2 and 10,0 and 10,0 b.	starting any has no ell. " 00'. rawn. the
The sub other e The She casing Present We will 1. 2. 3. 4. 5. 6. 7. 8. 9.	ject well conomic re by Federa to 10,508 open perf use the f MIRUSU an Set a CIE Set a CIE Cut the 4 plug at 8 Spot a 15 Spot a 15 Spot a 10 at 3450'. Spot a 20 to the Ca	is dep: complet 1 #1 ha (TOC= { foration followin d wire: 5P @ 90! -1/2" d 325'. 0' plu; 0' plu; 0' plu; 0' plu; 0' plu;	leted in i tion possi as 13-3/8" 3440 by CB ns are 946 ng procedu line. Call 00' and du casing at g 7650-750 g 5650-550 g 3550-345 g 1770-147 g 500-300' Reef.	ts present p bilities, so casing to 3 3L). It also of'-78' (Atok are to plugan BLM in Carl mp 35' cemer + 8400'. Spo 0 at the top 0 at the top 0 at the top 0 across the const the top	(Nor: Report Completion or R Completion or R details, and give pertinent oroducing zones (S we propose to pl 55', 8-5/8" casin has bridge plugs a) and 9094-9100 and abandon this we sbad: 1-505-887-6 at on top to sepan at on top to sepan at on top to isola of the Wolfcamp of the Wolfcamp of the 2nd Bone shoe of the 8-5/ the top of the I 13-3/8" casing sh	ecompletion B dates, includi vertical depth Strawn and ug and a ig to 350 s at 10,1 (Strawn) ell: 5544. tate the folug 8475 Spring s (8" casin Delaware and t	<pre>import and Log form.) ing estimated date of ing for all markers and abandon the w O6' and 4-1/2 330' and 10,0). Atoka and St Strawn. 5'-8325'. Tag sand. ng. Tag the p . to isolate th</pre>	starting any has no ell. " 00'. rawn. the lug e top
17. DESCRIDING proponent to The sub other e The She casing Present We will 1. 2. 3. 4. 5. 6. 7. 8. 9. 10.	ject well conomic re- lby Federa to 10,508 open perf use the f MIRUSU an Set a CIE Set a CIE Set a CIE Cut the 4 plug at 8 Spot a 15 Spot a 10 Spot a 10 Spot a 20 to the Ca Spot a 50 to instal Union Tex	is dep: is dep: complet if #1 ha (TOC= { foration foration for at ion for at ion	leted in i tion possi as 13-3/8" 3440 by CB as are 946 ag procedu line. Call 00' and du casing at g 7650-750 g 5650-550 g 3550-345 g 1770-147 g 500-300' Reef. ace plug 5 l marker t roleum Cor	ts present p bilities, so casing to 3 3L). It also of '-78' (Atok are to plugan BLM in Carl mp 35' cemer + 8400'. Spo 0 at the top 0 at the top 0 at the top 0 across the co surface. o extend 4' p, Shelby Fed	(Nor: Report I Completion or R details, and give pertinent oroducing zones (S we propose to pl 55', 8-5/8" casin b has bridge plugs a) and 9094-9100 and abandon this we sbad: 1-505-887-6 at on top to sepan at on top to isola of the Wolfcamp of the Wolfcamp of the 2nd Bone e shoe of the 8-5/ the top of the I 13-3/8" casing sh Cut casing 3' be above ground leve eral #1, Unit H,	ecompletion B dates, includi vertical depth Strawn and and to 350 s at 10,1 (Strawn) ell: 5544. tate the folug 8475 Spring s (8" casin Delaware and the elow surf ell. Market Sec.13,7	Atoka and St Strawn. 5'-8325'. Tag sand. ng. Tag the p to isolate th face. Weld ca er should ind	starting any has no ell. " 00'. rawn. the lug e top p icate e plugged.
17. DESCRIDI proponent 1 The sub other e The She casing Present We will 1. 2. 3. 4. 5. 6. 7. 8. 9. 10.	ject well conomic re lby Federa to 10,508 open perf use the f MIRUSU an Set a CIE Set a CIE Set a CIE Cut the 4 plug at 8 Spot a 15 Spot a 10 Spot a 10 Spot a 10 at 3450'. Spot a 20 to the Ca Spot a 50 to instal Union Tex certify that the s are atta	is dep: is dep: complet if #1 ha (TOC= { foration foration for at ion for at ion	leted in i tion possi as 13-3/8" 3440 by CB as are 946 ag procedu line. Call 00' and du casing at g 7650-750 g 5650-550 g 3550-345 g 1770-147 g 500-300' Reef. ace plug 5 l marker t roleum Cor	ts present p bilities, so casing to 3 L). It also 7'-78' (Atok re to plugan BLM in Carl mp 35' cemen + 8400'. Spo 0 at the top 0 at the top 1 at the top 0 at the top 1 at the top 0 at the top 1 at the	(Nor: Report Completion or R details, and give pertinent oroducing zones (S we propose to pl 55', 8-5/8" casin has bridge plugs a) and 9094-9100 and abandon this we sbad: 1-505-887-6 at on top to sepan at on top to sepan at on top to isola of the Wolfcamp of the Wolfcamp of the 2nd Bone shoe of the 8-57 the top of the I 13-3/8" casing st Cut casing 3' be	ecompletion B dates, includi vertical depth Strawn and ang to 350 s at 10,2 (Strawn) ell: 5544. cate the file the Solug 8475 Spring s (8" casin Delaware hoe and t elow surf el. Marke Sec.13,7 h. Note:	eport and Log form.) Ing estimated date of a for all markers and abandon the w 06' and 4-1/2 330' and 10,0). Atoka and St Strawn. 5'-8325'. Tag sand. ng. Tag the p to isolate th face. Weld ca er should ind T22S,R24E,Dat Before and a	<pre>starting any starting any has no ell. " 00'. " oo'. " the lug e top p icate e plugged. fter well</pre>
17. DESCRIDI proponent 1 The sub other e The She casing Present We will 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 8. 1 hereby sketche siGNED	ject well conomic re lby Federa to 10,508 open perf use the f MIRUSU an Set a CIE Set a CIE Set a CIE Cut the 4 plug at 8 Spot a 15 Spot a 10 Spot a 10 Spot a 10 at 3450'. Spot a 20 to the Ca Spot a 50 to instal Union Tex certify that the s are atta	is depl is depl complet (TOC= { foration followin d wire p @ 940 p @ 909 -1/2" d 325'. 0' plus 0' plus 0' plus 0' plus 0' plus 1 steel ched. I foregoing 1 ched. I	leted in i tion possi as 13-3/8" 3440 by CB ns are 946 ng procedu line. Call 00' and du casing at 3550-750 3550-750 3550-345 3550-345 3550-345 3500-300' Reef. ace plug 5 1 marker t coleum Cor s true and corrections	ts present p bilities, so casing to 3 L). It also 7'-78' (Atok re to plugan BLM in Carl mp 35' cemen + 8400'. Spo 0 at the top 0 at the top 1 at the top 0 at the top 1 at the top 0 at the top 1 at the	(Nor: Report Completion or R details, and give pertinent oroducing zones (S we propose to pl 55', 8-5/8" casin b has bridge plugs a) and 9094-9100 and abandon this we sbad: 1-505-887-6 at on top to sepan at on top to isola of the Volfcamp of the Wolfcamp of the 2nd Bone shoe of the 8-57 the top of the I 13-3/8" casing sh Cut casing 3' be above ground leve eral #1, Unit H, U. Clean Location y by Bob Pitschke	ecompletion B dates, includi vertical depth Strawn and ang to 350 s at 10,2 (Strawn) ell: 5544. cate the file the Solug 8475 Spring s (8" casin Delaware hoe and t elow surf el. Marke Sec.13,7 h. Note:	Atoka and St Strawn. 5'-8325'. Tag sand. ng. Tag the p to isolate th face. Weld ca er should ind 122S,R24E,Dat Before and a DATE3-3-86	e top p icate e plugged.
17. DESCRIDI proponent I The sub other e The She casing Present We will 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 8. I hereby sketche signed	ject well conomic re lby Federa to 10,508 open perf use the f MIRUSU an Set a CIE Set a CIE Set a CIE Cut the 4 plug at 8 Spot a 15 Spot a 15 Spot a 15 Spot a 10 at 3450'. Spot a 30 Spot a 20 to the Ca Spot a 50 to instal Union Tex certify that the	is depl is depl complet (TOC= { foration followin d wire p @ 940 p @ 909 -1/2" d 325'. 0' plus 0' plus 0' plus 0' plus 0' plus 1 steel ched. I foregoing 1 ched. I	leted in i tion possi as 13-3/8" 3440 by CB ns are 946 ng procedu line. Call 00' and du casing at 3550-750 3550-750 3550-345 3550-345 3550-345 3500-300' Reef. ace plug 5 1 marker t coleum Cor s true and corrections	ts present p bilities, so casing to 3 L). It also 7'-78' (Atok re to plugan BLM in Carl mp 35' cemen + 8400'. Spo 0 at the top 0 at the top 1 at the top 0 at the top 1 at the top 0 at the top 1 at the	(Nor: Report Completion or R details, and give pertinent oroducing zones (S we propose to pl 55', 8-5/8" casin b has bridge plugs a) and 9094-9100 and abandon this we sbad: 1-505-887-6 at on top to sepan at on top to isola of the Volfcamp of the Wolfcamp of the 2nd Bone shoe of the 8-57 the top of the I 13-3/8" casing sh Cut casing 3' be above ground leve eral #1, Unit H, U. Clean Location y by Bob Pitschke	ecompletion B dates, includi vertical depth Strawn and ang to 350 s at 10,2 (Strawn) ell: 5544. cate the file the Solug 8475 Spring s (8" casin Delaware hoe and t elow surf el. Marke Sec.13,7 h. Note:	eport and Log form.) Ing estimated date of a for all markers and abandon the w 06' and 4-1/2 330' and 10,0). Atoka and St Strawn. 5'-8325'. Tag sand. ng. Tag the p to isolate th face. Weld ca er should ind T22S,R24E,Dat Before and a	e top p icate e plugged.

*See Instructions on Reverse Side