

Bennett Wire Line Service

305 MCARTHUR AVENUE • PHONE 746-3281

ARTESIA, NEW MEXICO 88210

7/20/74

RECEIVED

AUG 19 1974

O. C. C.
ARTESIA, NEW MEXICO

Corinne grace; re- GoPo Go No.1

The reason for not being able to record flowing pressures while going in the hole was, the pipeline company notified me of their compressor being down.

The pressures obtained while compressor being down, would not have been normal, so ran on to bottom and shut the well in for the 48 hour build-up.

Thank you

E. D. Bennett