RECEIVED

HILLIN PRODUCTION CO.

P. O. BOX 2889 ODESSA, TEXAS 79760

AREA 915 837-8242

9 April 1973

APR 1 0 1973

C. C. C.

Oil Conservation Commission State of New Mexico P.O. Drawer DD Artesia, New Mexico 88210

Attention: Mr. W.A. Gressett

Dear Mr. Gressett,

As per our telephone conversation, the change in cementing of intermediate from 600 sacks to 150 sacks occured due to my not knowing the report filed by my son had set out the said 600 sacks as he had done on the "D.W.U." well. I cemented the "J.C.W. state #1." well in the same manner as the "Dero Federal" well which is producing from the "Morrow" as a direct offset to my well. Since we did not have any sign of the "reef" or any lost circulation of any kind, I thought this to be adequate. I apologize for the mix-up and request approval of cementing of 8 5/8" as it was done since oil string has been cemented & well is being completed.

Thank you for your consideration in this matter.

Sincerely,

Ph Hillin

R.N. Hillin

RNH/ab