	N.M.O.C.D.	COLT		c/si
DEPARTN T OF THE INTERIOR verse side)			ATE. Form approv	eu. Filer
			on re- Budget Bure 5. LEASE DESIGNATION	AND SEBIAL NO.
GEOLOGICAL	. SURVEY		NM 7068	
SUNDRY NOTICES AND	REPORTS ON	WELLS	6. IF INDIAN, ALLOTTE	E OR TRIBE NAME
(100 not use this form for proposals to drill or to	deepen an ato 1 1	to a different reservoir		
Use "APPLICATION FOR PERM	AlT-" for such propos	als.) RECIVED		
OIL GAS WELL WELL OTHER			7. UNIT AGREEMENT NA	ME
2. NAME OF OPERATOR			a	
Monsanto Company 🦯			S. FARM OR LEASE NAM	
3. ADDRESS OF OPERATOR		- 0. c p. -	9. WELL NO.	cal
1330 Midland NBT, Midland, Tx.	79701	ARTESIA, OFFICE	1	
 LOCATION OF WELL (Report location clearly and in acco See also space 17 below.) At surface 	rdance with any State	e requirements.*	10. FIELD AND POOL, O	WILDCAT
			Burton Flat-M	lorrow Atoka
1600' FNL & 1980' FEL			11. SEC., T., R., M., OR E SURVEY OR AREA	LK. AND
		11.		0 0 0 7 7
14. PERMIT NO. 15. ELEVATIONS	(Show whether DF, RT, (Sec. 3, T-21 12. COUNTY OB PARISH	
3199 D		· ·	Eddy	N.M.
16. Check Appropriate Bay	To Indiana NL			[N • P1 •
16. Check Appropriate Box	to indicate Natur	e of Notice, Report,	or Other Data	
		S U	BSEQUENT REPORT OF:	
TEST WATER SHUT-OFF PULL OR ALTER CAN	SING	WATER SHUT-OFF	BEPAIRING W	ELI,
FRACTURE TREAT MULTIPLE COMPLET SHOOT OR ACIDIZE ABANDON*	(E	FRACTURE TREATMENT	ALTERING CA	SING
REPAIR WELL CHANGE PLANS		SHOOTING OR ACIDIZING	ABANDONMEN	т*
(Other)		(Other) (Note: Report re	sults of multiple completion of	
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s proposed work. If well is directionally drilled, give nent to this work). 	state all pertinent det	Completion of Rec	completion Report and Log for.	m.)
proposed work. If well is directionally drilled, give nent to this work.) •	subsurface locations :	and measured and true v	ertical depths for all markers	and zones perti-
1) Set 50 Sxs plug on top of Perr	n Latch Packe	r .	` .	
2) Set CIBP @ 10,300' with 50 Sxs	s on ton		-	
3) If 5 1/2" casing is cut off by	elow 8760!	et 150' plug 75	in casing	
75 Out of Scup, Then set 150	J' DING (8760	'-8610') Tf -	ut off above	
3,00, $3,00$, 100 , 100 , 100 , 100 , 100	casing 75' o	ut of stub.		
4) Set 150' plug @ 7000'. 5) Set 150' plug top of Barg Sand		• •		· · ·
5) Set 150' plug top of Bone Spri 6) Set 100' plug 50'in and 50' ou	lngs(5160'-50)	10').		·
7) 15 Sx plug at surface with 4 f	it of 9 5/8 ca	asing @ 2788!.		
Work will start approximately 1	L 1/ 15/80			
RE			RECEIVED	
			SEP 1 7 1980	
		<u>لل</u>	S. GEULUGICAL SURVEY	
		l	ARTESIA, NEW MEXICO	
18. I hereby certify that the foregoing is true and correct				
SIGNED CHE C Mobel	TITLE Regiona	al Prod. Engr.	DATE9/11/	80
(This space for Federal or State office use)				
APPROVED (Orig. Sgd.) PETER W. CHESTER	ANTINO	NICTRICT		0.0.000
CONDITIONS OF APPROVAL, IF ANY:	TITLE	DISTRICT ENGINES	R DATE OCI	2 0 1980

ľ