DUAL OR MULTIPLE COMPLETION DATA SHEET

Coquina ail Corp. Yates State #1- K-10-21-27

Operator 9-5-73 Well S.T.R.

Order No. MC 2060 Pools Button Hat morrow to

PACKER LEAKAGE TEST DATA

Test	Date	Approval Date	Test Date	Approval Date
1-9-	10-74	1-17-74	·	
	1675	12-2-75 8		
6-27	-7-2-76	7-15-76		
1/20-	24/78	1/25/78		
	9/78	. 12/8/78		
6/5/		6/27/79		
·				•

λ <u></u>	~ 6127
Submit 3 Copies To Appropriate District Office State of New Mexico	o Form C-103
Submit 3 Copies To Appropriate District Office District I 1625 N. French Dr., Hobbs, NA 88210 District II 1301 W. Grand Ave., Arcsin, NM 88210 District III 1000 Rio Brazos Rd State of New Mexico State of New Mexico Conservation District III 1220 South St. Francis	Resources Revised March 25, 1999 WELL API NO.
District II	30-015-20838
District III 2 2000 2000 2000 SERVATION DI	5. Indicate Type of Lease
1000 Rd Dazzos Rd., 4440, RM OVEN	STATE STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr. Santa Fe, NM-CEIVED 87505 OCD - ARTESIA	K-3977
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DEFPEN OR PLUG B	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO PRILL OR TO DEEPEN OR PLUG B DIFFERENT RESERVOIR. "PROPOSALS." (FORM C-101) FOR SU PROPOSALS.)	YATES STATE
Type of Well: Oil Well	
2. Name of Operator CHI OPERATNG, INC.	8. Well No.
3. Address of Operator	9. Pool name or Wildcat
P.O. BOX 1799 MIDLAND, TEXAS 79702 4. Well Location	BURTON FLAT MORROW
4. Well Location	
Unit Letter <u>K</u> : <u>1980</u> feet from the <u>SOUTH</u> line and	d 1980 feet from the WEST line
	e 27E NMPM EDDY County
10. Elevation (Show whether DR, R. 3275' KB	KB, RT, GR, etc.)
11. Check Appropriate Box to Indicate Natur	re of Notice. Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON RE	EMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☑ CHANGE PLANS ☐ CO	OMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
— — — — — — — — — — — — — — — — — — —	ASING TEST AND EMENT JOB
OTHER:	THER:
12. Describe proposed or completed operations. (Clearly state all pertinen	
starting any proposed work). SEE RULE 1103. For Multiple Complete	ions: Attach wellbore diagram of proposed completion or
recompilation.	E 11 400'
Release packer @ 11,195'. TOH with tubing & packer. Set CIBP above M	forrow perforations, thus temporarily abandoning the wellbore.
1/35'cm1 Sct C760 @ 10200'	
Schedule test 24 hours in advance with	
OCD. 505-748-1283. Test to 500# for thirty	
minutes. A pressure drop of not greater than	
10% will be allowed.	
OCD must witness test.	
I hereby certify that the information above is true and complete to the best of	of my knowledge and belief.
SIGNATURE TITLE	DATE 2/18/07
Type or print name Joth W- WOLF	Telephone No. 5/5-685-500/
(This space for State use)	Iild Dep IP FEB 2 1 2002
APPPROVED BY TITLE Conditions of approval, if any:	DATE ED 2 1 ZUUS

Wel Uni	t K Section 10 Township 21 Rai # 30-015 20838
	760' Senjea Plug
33/8 1012 Cine	4- Shor Plug 562'- 75
95/8 2000 Circ	- shoe Plug 2950' 3050' - tag
9540	+ 6500' + 8700' +00 0 50% + 10,700'- TA; Perts 11,300'- TA;
11454	Parts

1015
-Г. Salt
B. Salt
Yates
Glorieta
Delaware 2900
Bone Sp. 5165
Abo
Wolfcamp 8759
Morrow 10920
Devonian
Fusselman
Other

TOPS

- Contact OCD 24 hrs. prior to any work done.
- Salt gel mud consisting of 10# brine with 25# of gel per barrel must be placed between each plug
- Install dry hole marker as per rule 202.B.2
- Plugs are to be set from point indicated up
- Plugs must not be less than 100' or 25 Sacks of cement, whichever is greater, unless specifically indicated.
- Shoe and stub plugs will be 50' above and below shoe or stub and tagged.
- Surface plug will be from 0'- 60'
- Where plugs are required cement must be placed inside and outside of all casing string(s), in the correct footage or sacks required, if no cement exists.
- Plugs to be tagged will be indicated.