

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE
(Other instructions
reverse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Manzano Oil Corporation 505/623-1996

SEP 19 '88

3. ADDRESS OF OPERATOR
P.O. Box 2107/Roswell, NM 88202-2107 O. C. D.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

660' FNL & 1650' FEL Sec 8 21S 27E

14. PERMIT NO.
30-015-20877

15. ELEVATIONS (Show whether SP, ST, OR, etc.)
3275' GR

5. LEASE DESIGNATION AND SERIAL NO.
NM-56530

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Radke Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Cedar Hills-Bone Spring

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA
Sec 8 T21S R27E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☒
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We request approval to plug and abandon this well as follows:

Set CIBP at 7200' with 35' of cement on top.
Set CIBP at 6400' with 35' of cement on top.
Cut 4-1/2" casing at approximately 4500' and pull.
Set 75' cement in and out of 4-1/2" casing stub (150' cement). Tag cement.
Set 50' cement in and out of 9-5/8" casing @ 2600'. (100' cement).
Set 50' cement in and out of 13-3/8" casing @ 605'. (100' cement).
Set 50' plug at surface and install dry hole marker.
Restore surface as set out in regulations.

18. I hereby certify that the foregoing is true and correct

SIGNED

Jackie Midkiff

TITLE Jackie Midkiff/Landwoman

DATE 8/30/88

(This space for Federal or State office use)

APPROVED BY CRIG, SGD, RAJ GIRI

TITLE

DATE

9-16-88

CONDITIONS OF APPROVAL BY RESOURCES

*See Instructions on Reverse Side