		manager and the base		
		 COMMILS (1) 		
	Artesia. N	4 18210	۰۰, ۱ ۰	
vrm 3160-5	UNITED 5	TATES		FORM APPROVED Budget Bureau No. 1004–0135
une (1990)	DEPARTMENT OF			Expires: March 31, 1993 5. Lease Designation and Serial No.
	BUREAU OF LAND	MANAGEMENT	RUC	NNI-12388-A
SU	INDRY NOTICES AND	REPORTS ON WELL	S	6. If Indian, Allottee or Tribe Name
Do not use this form	for proposals to drill or to	o deepen or reentry to	a different reserve	oir.
Use '	APPLICATION FOR PER	MIT—" for such propos	ais	7. If Unit or CA, Agreement Designation
	SUBMIT IN TH	RIPLICATE		7. If that of CA, Aground Cargan
Type of Well				8. Well Name and No.
Oil Well X Gas	Other			Rocky Arroyo "C" Com #1
2. Name of Operator			101	9. API Well No.
D.M.S. Oil Compa 3. Address and Telephone No.	.ny		the second second	
3000 Wilcrest, Sui		ston, Texas 77042		10. Field and Pool, or Exploratory Area
4 Location of Well (Footage, Se	ec., T., R., M., or Survey Description	:)	. + 2 3 ⁽¹⁾ - W (4) (4)	11. County or Parish, State
Sec 8 T-22-S R-2	22-E 1980 FNL 1980	FWL		
				Eddy, New Mexico
CHECK AP	PROPRIATE BOX(s) TO	INDICATE NATURE	OF NOTICE, RE	PORT, OR OTHER DATA
TYPE OF SUE			TYPE OF ACT	
		Abandonment		Change of Plans
		Recompletion		New Construction
Subsequent R	Report	Plugging Back		Non-Routine Fracturing Water Shut-Off
		Casing Repair		Conversion to Injection
Final Abando	onment Notice	Other		Dispose Water
				(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13 Describe Proposed or Comple	eted Operations (Clearly state all pertine is and measured and true vertical depth	int details, and give pertinent dates, to for all markers and zones pertin	including estimated date of ent to this work.)*	f starting any proposed work. If well is directionally drilled
2) T.I.H. W/dum	ing unit T.O.H. W/Pro p bailer and cap C.I.B	.P. at 7280' W/35' Ce	ement	
 4) Load hole W/r 5) Cut and pull 5 6) Spot 150' cem 7) Spot 130' cem 8) Spot 100' cem 9) Spot and pull 10) Spot 100' cem 11) Spot 100' cem 	B.P. at 7100' and cap	W/35' cement 000' plus or minus o and tag 50' e 1900' - 1800' and t pint IF no circulated approx. 800' and ta pe 235' - 135' and ta	ag j W/cement g	
 4) Load hole W/r 5) Cut and pull 5 6) Spot 150' cem 7) Spot 130' cem 8) Spot 100' cem 9) Spot and pull 10) Spot 100' cem 11) Spot 100' cem 12) Spot 50' surfa This is 14. Thereby certify that the toil Signed Legendaria (This space for Federal or Approved by Helease 	B.P. at 7100' and cap mud 5 1/2 casing approx. 40 hent plug at 5 1/2 stub hent plug at 3185' - 30 hent plug at 9 5/8 shoe 9 5/8 casing at freepo hent plug at 9 5/8 stub hent plug at 9 5/8 stub hent plug at 13 3/8 sho hert	W/35' cement 000' plus or minus and tag 50' e 1900' - 1800' and t pint IF no circulated approx. 800' and ta be 235' - 135' and ta narker	ag 1 W/cement g g <u></u> <u>Mg</u>	Date $6 - 1 - 93$ EER Date $6 - (-93)$
 4) Load hole W/r 5) Cut and pull 5 6) Spot 150' cem 7) Spot 130' cem 8) Spot 100' cem 9) Spot and pull 10) Spot 100' cem 11) Spot 100' cem 12) Spot 50' surfa This is 14. Thereby certify that the toil Signed Curristics (This space for Federal or Approved by Homes of approval. if 	B.P. at 7100' and cap mud 5 1/2 casing approx. 40 hent plug at 5 1/2 stub hent plug at 3185' - 30 hent plug at 9 5/8 shoe 9 5/8 casing at freepo hent plug at 9 5/8 stub hent plug at 9 5/8 stub hent plug at 13 3/8 sho hert	W/35' cement 000' plus or minus and tag 50' e 1900' – 1800' and t bint IF no circulated approx. 800' and ta be 235' – 135' and ta narker TAL Title	ag 1 W/cement g g <u></u> <u>Mg</u>	Date $6 - 1 - 93$ EER Date $6 - 1 - 93$

*See Instruction on Reverse Side

BUREAU OF LAND MANAGEMENT CARLSBAD RESCURCE AREA

Permanent Abandonment of Wells on Federal Lands

- -

Conditions of Approval

1. <u>Approval:</u> Plugging operations shall commence within 90 days from the approval date of plugging procedure.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Eddy County call (505)887-6544 ; for wells in Lea County call (505) 373-3612.

3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate. shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22.727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C", for up to 7,500 feet of depth, mixed at 14.8 lbs./gal. with 6.3 gallons of fresh water per sack or class "H", for deeper than 7,500 feet plugs, mixed at 15.4 lbs./gal. with 4.3 gallons of fresh water per sack.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).

7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show <u>date</u> well was plugged.

~ .

*

Following the submittal and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.



CONVERSION FACTCRS

Ft.

MULTIPLY	By	TO OBTAIN
Barrels Cubic Feet Gallons Pounds/gal.	7.4806 0.1337	Cubic Feet Gallons Cubic Feet Pounds/Cu.

PIPE VOLUMES

 $0.00545 \times 1.D.^2$ in inches = Cu. Ft./Ft. $0.0407 \times 1.D.^2$ in inches = Gals./Ft. $0.00097 \times 1.D.^2$ in inches = Bbls./Ft.

HYDROSTATIC PRESSURE FOR WATER: 0.434 x Depth in Feet = PSI. FOR OTHER FLUIDS: 0.434 x Depth x Sp. Gr. = PSI.





07 3183 - 3050 130 phun

5/12 Stub 4000 ton - TA9 150' plag at ĩ v k . 76 Bridge Flug w/ 35 convert At 7100 145 417280 Rindge Phage w/35 Commer CAP r 72 47 8468 W/ Hydremit : SAND phog Otis PKR ٨F 38-521 1/2 9255

"AFTER"

CONVERSION FACTORS

MULTIPLY	Ву	T
Barrels	5.6146	С
Cubic Feet	7.4806	G
Gallons	0.1337	С
Pounds/gal.	7.4806	P

By TO CBTAIN 6146 Cubic Feet 4806 Gallons 1337 Cubic Feet 4806 Pour ds/Cu. Ft.

PIPE VOLUMES

 $0.00545 \times 1.D.^2$ in inches = Cu. Ft./Ft. $0.0407 \times 1.D.^2$ in inches = Gals./Ft. $0.00097 \times 1.D.^2$ in inches = Bbls./Ft. HYDROSTATIC PRESSURE FOR WATER: 0.434 x Depth in Feet = PSI. FOR OTHER FLUIDS: 0.434 x Depth x Sp. Gr. = PSI.

3