

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

JUN 19 1985

O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator MONSANTO OIL COMPANY ✓	8. Farm or Lease Name McNew Com
3. Address of Operator 1300 One First City Center, Midland, TX 79701	9. Well No. 1
4. Location of well UNIT LETTER <u>G</u> , <u>1604</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>5</u> TOWNSHIP <u>21-S</u> RANGE <u>26-E</u> NMPM.	10. Field and Pool, or Wildcat Avalon (Delaware)
15. Elevation (Show whether DF, RT, GR, etc.) 3186 GR	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Load hole w/9# brine.
- 2) Spot 100' cmt plug w/bottom of tubing @ 2050' (tag plug).
- 3) Spot 100' cmt plug w/bottom of tubing @ 550'.
- 4) Spot 30' cmt plug @ surface.
- 5) Weld plate on head. Clean up location.

Post ID-2
6-28-85
P+H

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Regional Production Manager DATE 6/12/85

APPROVED BY [Signature] TITLE Geologist DATE 9-18-85

CONDITIONS OF APPROVAL, IF ANY: