Ni IL CONS COMMISSION

D

rawer	DD	

Form 3160-5 (June 1990)	UNITED ST DEPARTMENT OF T BUREAU OF LAND I	THE INTERIOR	Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.
	SUNDRY NOTICES AND F	REPORTS ON WELLS deepen or reentry to a different reservoir.	LC-067144 6. If Indian, Allottee or Tribe Name
	SUBMIT IN TR	IPLICATE	7. If Unit or CA, Agreement Designation Big Eddy Unit
1. Type of Well Old X Well 2. Name of Operator Bass Enterpt	Dother	/	3. Well Name and No. Big Eddy Unit #41 9. API Well No.
Address and Telephone P. O. Box 2 Location of Weil (Foota			30-015-21325 10. Field and Pool, or Exploratory Area Wildcat (Atoka) 11. County or Farish, State
T-21-S, R-28	8-E		Eddy County, New Mexico
12. CHECK	APPROPRIATE BOX(s) TO I	NDICATE NATURE OF NOTICE, REPOR	RI, OR OTHER DATA
	SUBMISSION	TYPE OF ACTION	pincing.
X Notice	of Intent Jent Report	Abandonment Recompletion Plugging Back Casing Repair	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off
Final A	bandonment Notice	Altering Casing Action Temporarily Abandon	Conversion to Injection
Bass Enterp Big Eddy #4	ations and measured and true vertical depths for rises Production Co. re	etails, and give pertinent dates, including estimated date of starting or all markers and zones pertinent to this work.)* espectfully requests approval to plans to recomplete to the Bone October 1, 1995.	o temporarily abandon
-		g distribute	c 4
,			
	- 110 005 5/2		
	Z 112 327 740 - WHF:PGO foregoing is true and correct		
Signed City diar lie	Keith E. Bucy	Tide Division Production Supt.	
(This space for Federal QR? Approved by Conditions of approval,	G SGD) JOE G. LARA	Tide PETROLEUM ENGINEER	Date 3/10/95

BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

Temporary Abandonment of Wells on Federal Lands

Conditions of Approval

Temporary Abandonment (TA) status approval requires: A) Successful Casing Integrity Test and,

B) Successful Bradenhead Test.

Any temporary abandonment request must be submitted on a Sundry Notice (Form 3160-5), one (1) original signature and five (5) copies, and include the following:

- Justification why the well should be temporarily abandoned rather than permanently plugged and abandoned.
- 2. Description of the temporary abandonment procedure.
- 3. A complete wellbore diagram shown as temporarily abandoned.
- 4. The anticipated date the operations will occur.

Contact the appropriate BLM office at least 48 hours prior to the scheduled Casing Integrity and the Bradenhead Tests. For wells in Eddy County call (505) 887-6544; for wells in Lea County call (505) 393-3612.

A) Casing Integrity Test for TA:

- 1. Install an isolation device (such as a retainer or bridge plug) within 50' to 100' of the top perforation or cement plug that extends at least 50' above each set of open perforations. Unless prior approval is granted by the Authorized Officer, fill the well bore with conditioned, non-corrosive fluid and shut-in at the surface. If a cement plug is used, the top of the cement must be verified by tagging. If the wellbore had more than one producing horizon, the lower set(s) of perforations or open hole must meet the requirements for permanent plug to abandonment, unless justification is provided by the operator not to do so.
- 2. A test demonstrating casing mechanical integrity is required. An approved method is a pressure test of the casing and uppermost plug. The pressure test conducted shall be a minimum of 500 psi surface pressure with less than 10 percent pressure drop within thirty (30) minutes. In no event shall the pressure test required exceed seventy (70) percent of the internal yield of the casing. In the case of an unsuccessful test, the operator shall either correct the problem or plan to plug and abandon the well. Alternative methods demonstrating casing mechanical integrity may be approved by the Authorized Officer on a case-by-case basis.

B) Bradenhead Test for TA:

- 1. Record the pressure measured on each casing string, including intermediate casing, using deadweight or calibrated pressure gauge.
- 2. Open the bradenhead valve to the atmosphere. If gas or water flow is observed or indicated, flow the bradenhead for a minimum of fifteen (15) minutes and record pressures at five (5) minute intervals on the production, intermediate and surface casing. Describe in detail any fluids flowing from the bradenhead including measured or estimated rates of flow. A water and/or gas analysis may be required.

Wells that successfully pass the casing integrity test and the bradenhead test will be approved for Temporary Abandonment (TA) status for 12 months provided that the operator:

- 1. Submits within thirty (30) days a subsequent Sundry Notice (one (1) original signature and five (5) copies) requesting TA approval,
- 2.Attaches a clear copy or the original of the pressure test charts,

If the well does not pass the casing integrity test and/or the bradenhead test, then the operator shall within 90 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.