Porm 5-331 (May 1963) UN'TED STATES DEPARTME OF THE INTERIOR Verse side) GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS				E* Form approve Budget Bures	u No. 42-R1424.	
				NM - 040087		
				6. IF INDIAN, ALLOTTER		
	proposals to drill or to deeper PLICATION FOR PERMIT—"					
			ECEIVEI	7. UNIT AGREEMENT NA	мв	
OIL GAS WELL OTH	ER			B. FARM OR LEASE NAM	······	
Atlantic Richfield Company - JUN 1 0 1975					BO-2 Federal Com.	
ADDRESS OF OPERATOR			. .	9. WBLL NO.		
P. O. Box 1710, Hobbs, New Mexico 88240						
				10. FIELD AND POOL, OF	Avalon Morrow Gas	
660' FSL & 1980' FE	L (Unit letter O)					
4. PERMIT NO. 15. ELEVATIONS (Show whether DF, ET, GR, etc.)				9-21S-26E	13. STATE	
	3280.6			Eddy	N.M.	
B. Charl			of Notice Design		1 14 111 1	
	k Appropriate Box To In	aicate Nature				
	INTENTION TO:		1	EQUENT REPORT OF :		
TEST WATER SHUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF	BEPAIRING W		
SHOOT OR ACIDIZE	MULTIPLE COMPLETE ABANDON*		FRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING CA	11	
REPAIR WELL	CHANGE PLANS		(Other)			
(Other) Dual Com	plete	X	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
3. Perforate Atoka		to recepta				
 Continue in hole Run choke to put Treat Atoka thru Flow back Atoka Bull choko & flow 	upper zone in tbg perfs 10170-176' & treat.	w/1000 ga	ls MS acid @ max	rate using 1000		
5. Run choke to put 6. Treat Atoka thru	upper zone in tb perfs 10170-176' & treat. w Atoka thru tbg {	w/1000 ga	ls MS acid @ max	rate using 1000		
 Fun choke to put Treat Atoka thru Flow back Atoka Pull choke & flow Pull plug from response 	upper zone in tbg perfs 10170-176' & treat. w Atoka thru tbg { eceptacle.	w/1000 ga & csg to c	ls MS acid @ max lean up.	rate using 1000		
 Fun choke to put Treat Atoka thru Flow back Atoka Pull choke & flow Pull plug from response 	upper zone in tbg perfs 10170-176' & treat. w Atoka thru tbg { eceptacle.	w/1000 ga & csg to c	ls MS acid @ max lean up.	rate using 1000		
 Run choke to put Treat Atoka thru Flow back Atoka Pull choke & flow Pull plug from response 	upper zone in tbg perfs 10170-176' & treat. w Atoka thru tbg { eceptacle.	w/1000 ga & csg to c	ls MS acid @ max lean up.	rate using 1000		
 Run choke to put Treat Atoka thru Flow back Atoka Pull choke & flow Pull plug from response 	upper zone in tbg perfs 10170-176' & treat. w Atoka thru tbg { eceptacle.	w/1000 ga & csg to c	ls MS acid @ max lean up.	rate using 1000		
 Fun choke to put Treat Atoka thru Flow back Atoka Pull choke & flow Pull plug from response 	upper zone in tbg perfs 10170-176' & treat. w Atoka thru tbg { eceptacle.	w/1000 ga & csg to c	ls MS acid @ max lean up.	rate using 1000		
 Fun choke to put Treat Atoka thru Flow back Atoka Pull choke & flow Pull plug from response 	upper zone in tbg perfs 10170-176' & treat. w Atoka thru tbg { eceptacle.	w/1000 ga & csg to c	ls MS acid @ max lean up.	rate using 1000		
5. Run choke to put 6. Treat Atoka thru 7. Flow back Atoka 8. Pull choke & flo 9. Pull plug from r 10. Run cross-over &	upper zone in tbg perfs 10170-176' & treat. w Atoka thru tbg & eceptacle. flow Morrow Gas :	w/1000 ga & csg to c in csg & A	ls MS acid @ max lean up. toka in tbg.) ft ³ N ₂ /bb	
5. Run choke to put 6. Treat Atoka thru 7. Flow back Atoka 8. Pull choke & flo 9. Pull plug from r 10. Run cross-over &	upper zone in the perfs 10170-176' & treat. w Atoka thru thg & eceptacle. flow Morrow Gas :	w/1000 ga & csg to c in csg & A	ls MS acid @ max lean up.) ft ³ N ₂ /bb	
 Run choke to put Treat Atoka thru Flow back Atoka Pull choke & flow Pull plug from r Run cross-over & 	upper zone in tbg perfs 10170-176' & treat. w Atoka thru tbg & eceptacle. flow Morrow Gas :	w/1000 ga & csg to c in csg & A	ls MS acid @ max lean up. toka in tbg.) ft ³ N ₂ /bb	
 5. Run choke to put 6. Treat Atoka thru 7. Flow back Atoka 8. Pull choke & flow 9. Pull plug from r 10. Run cross-over & 8. I hereby certify that the foregoing signed	upper zone in tbg perfs 10170-176' & treat. w Atoka thru tbg & eceptacle. flow Morrow Gas : oling is true and correct 	w/1000 ga & csg to c in csg & A	ls MS acid @ max lean up. toka in tbg.) ft ³ N ₂ /bb	
 5. Run choke to put 6. Treat Atoka thru 7. Flow back Atoka 8. Pull choke & flor 9. Pull plug from r 10. Run cross-over & 8. I hereby certify that the foregoing signed	upper zone in tbg perfs 10170-176' & treat. w Atoka thru tbg & eceptacle. flow Morrow Gas : oling is true and correct 	w/1000 ga & csg to c in csg & A TLE	ls MS acid @ max lean up. toka in tbg.	7. DATE 6/5/) ft ³ N ₂ /bb	
 5. Run choke to put 6. Treat Atoka thru 7. Flow back Atoka 8. Pull choke & flow 9. Pull plug from r 10. Run cross-over & (8. I hereby certify that the foregoing signed	upper zone in tbg perfs 10170-176' & treat. w Atoka thru tbg & eceptacle. flow Morrow Gas : flow Morrow Gas : flow for row Gas :	w/1000 ga & csg to c in csg & A TLE	ls MS acid @ max lean up. toka in tbg. <u>Dist. Drlg. Supv</u>	7. DATE 6/5/) ft ³ N ₂ /bb	

-