une 1990)	DEPARTMENT OF BUREAU OF LAND		let a NM	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5: Lease Designation and Serial No. NM-0560291
o not use this form for pr	oposals to drill or to	EPORTS ON WELLS deepen or reentry to a di RMIT-" for such proposals	fferent resen	6. If Indian, Allottee or Tribe Name
	SUBMIT IN TR	IPLICATE		7. If Unit or CA, Agreement Designation
. Type of Well Oil Gas Well Well Othe	er			8. Well Name and No. Federal OO #2
Name of Operator V				9. API Well No.
Mewbourne Oil Company Address and Telephone No.				30-015-21433
P. O. Box 5270, Hobbs, NM 88241 (505) 393-5905			10. Field and Pool, or Exploratory Area	
L Location of Well (Footage, Sec., T., 660' FNL & 1980' FWL of Se	R., M., or Survey Description) action 18, T21S, R27E			Carlsbad Delaware 11. County or Parish, State Eddy
2. CHECK APPROF	PRIATE BOX(s) TO IN	IDICATE NATURE OF NO		
TYPE OF SUBMIS	SION	-	TYPE OF ACTI	ON
Notice of Intent		Abandonment		Change of Plans
— –		Recompletion		New Construction
Subsequent Report		Plugging Back Casing Repair		Water Shut-Off
Final Abandonmen	t Notice	Altering Casing		Conversion to Injection
		Other		Dispose Water
				(Note: Report results of multiple completion on Well
directionally drilled, give subsurfac 1) Abandon Strawn perforat	ions 10,024-030' by setti	ng a cast iron bridge plug at 10	a zonos poranona i	completion or Recompletion Report and Log form.) d date of starting any proposed work. If well is to this work.)* ping-20* of cement on top.
directionally drilled, give subsurfac	ions 10,024-030' by setti adding perforations 98	ng a cast iron bridge plug at 10	a zonos poranona i	d date of starting any proposed work. If well is to this work.)* ping.20 ⁺ of cement on top.
directionally drilled, give subsurfac 1) Abandon Strawn perforat 2) Test Canyon Formation b 3) Acidize Canyon perforation 3) Acidize Canyon perforation 4. I hereby certify that the foregoing Signed	is true and correct	ng a cast iron bridge plug at 10	a zonos poranona i	d date of starting any proposed work. If well is to this work.)* ping.20 ⁺ of cement on top.
directionally drilled, give subsurfac 1) Abandon Strawn perforat 2) Test Canyon Formation b 3) Acidize Canyon perforation 3) Acidize Canyon perforation 4. I hereby certify that the foregoing Signed	A locations and measured and tions 10,024-030' by setti by adding perforations 98 ons and test to evaluate.	ng a cast iron bridge plug at 10 44-64'.	a zonos poranona i	d date of starting any proposed work. If well is to this work.)* ping 20° of cement on top. 30° 1
directionally drilled, give subsurfac 1) Abandon Strawn perforat 2) Test Canyon Formation b 3) Acidize Canyon perforation 3) Acidize Canyon perforation 4) Acidize Canyon perforation 4) Acidize Canyon perforation 4) Acidize Canyon perforation 5) Acidize Canyon perforation	ta crime for any person knowi	ng a cast iron bridge plug at 10 44-64'.	b),000' and dum	d date of starting any proposed work. If well is o this work.)* ping 20° of cement on top. 30° '