



August 15, 1995

Mr. Ray Smith  
Field Rep Supervisor, District II  
State of New Mexico  
Oil Conservation Division  
Artesia District Office  
PO Drawer DD  
Artesia, New Mexico 88210

re: Toothman Gas Com. #1 L-25-21-27


Dear Mr. Smith,

Whiting Petroleum Corporation, as operator, recently received notification that a packer leakage test was required on the subject well. During July of 1995 we were attempting to set a plug in a profile beneath a sliding sleeve, open the sliding sleeve and allow the Wolfcamp to produce up the 2-7/8" tubing string. After numerous attempts to set plugs it became apparent there was a hole in the tubing. A service rig was moved on the well and the tubing and packer pulled. Since the Morrow has never produced in this well, rather than run a packer, a CIBP was set above the Morrow perforations. As a result of this work there is no packer to test.

The enclosed Sundry summarizes the work that was performed on the Toothman well.

Should you have any questions, or require additional information, do not hesitate to contact us.

Sincerely,  
Whiting Petroleum Corporation

  
James T. Brown  
Consulting Engineer

**WHITING PETROLEUM CORPORATION**

MILE HIGH CENTER, 1700 BROADWAY, SUITE 2300, DENVER, COLORADO 80290-2301 (303) 837-1661 FAX (303) 861-4023  
4804 REPUBLIC TOWERS II, 325 N. ST. PAUL ST., DALLAS, TX 75201 (214) 741-1650 FAX (214) 220-3940

An IES INDUSTRIES Company