Submit 3 Copies to Appropriate District Office

APPROVED BY -

State of New Mexico Energy, Minerals and Natural Resources Department

Form	C-103 ed 1-1-89	(
Revis	ed 1-1-89	ì

DISTRICT I	1000 11 11 17 / 000 10		WELL API NO.	WELL API NO.	
D. Box 1980, Hobbs, NM 88240 P.O. Box 2088		30-015	5-21578		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		5. Indicate Type of	STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas	Lesse No. (-5115	
CUNDOV NOT	CES AND REPORTS ON	WELLS			
(DO NOT USE THIS FORM FOR PRODIFFERENT RESERVED.)	DPOSALS TO DRILL OR TO DEP RVOIR. USE "APPLICATION FO -101) FOR SUCH PROPOSALS.	EPEN OR PLUG BACK TO PR PERMIT"	7. Lease Name or I	Unit Agreement Name	
1. Type of Well:		,	/		
OIL WELL X	OTHER	`	Stonewal	1 EP State Com	
2. Name of Operator			8. Well No.		
YATES PETROLEUM CORPOR	RATION			1	
3. Address of Operator		210	9. Pool name or W		
105 South Fourth Stree	et - Artesia, NM 882	210	Salada	r Strawn	
4. Well Location	0 37 .1	j	000		
Unit Letter F: 198	O Feet From The North	Line and $\frac{1}{2}$	980 Feet From	The West Line	
20	20C	- 20F		Eddy Courts	
Section 30	Township 20S	Range 28E heiher DF, RKB, RT, GR, etc.		Eddy County	
	//////////////////////////////////////	3282 GR	•	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	
	Maria De la Tali		a Damant on Othon	Dota	
	Appropriate Box to Indic				
NOTICE OF IN	rention to:	\$	SUBSEQUENT R	EPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	k 🗌	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	·	CASING TEST A	ND CEMENT JOB		
OTHER Repair casing leaks	s & acidize Strawn	X OTHER:			
			N 2 1 1 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1		
12. Describe Proposed or Completed Operwork) SEE RULE 1103. Propose to replace tub					
1. Attempt to load an					
tubing, packer and Var	in guns. (A) If pact	ker will not come	e loose, run fre	e point and fish	
for packer. (B) If ca					
If leak is above top of	of cement at 2600',	set RBP below lea	ak and dump 2 sa	cks of sand on top	
of RBP. Set retainer	50' above leak and	squeeze. If leal	k is above top c	f cement at 2600',	
a new procedure will b	e issued. WOC for	36 hours. TIH w	ith bit and dril	.1 out cement.	
Test casing to 1500 ps					
	ng tool and TOOH with				
	on/off tool to 10000	0'. Set packer a	and test annulus	to 1000 psi.	
Nipple down BOP and no		marm) riith 7500 i	and and aid wit	th CO2 and hall	
 Acidize perforations 	JIIS 100/9-1009/ (St.	Tawii) WILII /JOO)	gallons alcu wit	.ii CO2 and Daii	
	Put well back in pro	duction.			
2. 2	rate and the property of				
I hereby certify that the information above is tr	ue and complete to the best of my knowl	edge and belief.			
1 AKO.	.)		on Clerk	DATE 11-7-95	
SIGNATURE TUSING		mre		505-748-1471	
TYPEORPRINT NAME Rusty Klein	1			TELEPHONE NO.	
(This space for State Use)	RICAIRO DM TING ME MEINE				
	ESUPERVISOR			NOV 9 1995	