BUREAU LAND MANAGEMENT	r	<u>NM 3607</u>
SUNDRY NOTICES AND REPORTS @ (IDo not use this form for proposals to drill or to deepen or plug ba Use "APPLICATION FOR PERMIT-" for such pro	N & WELLS 88210	6. IF INDIAN, ALLOTTER OR TRIBE NAME
Um "APPLICATION FOR I Daniel		7. UNIT AGREEMENT NAME
OIL GAS WELL OTEER		8. PARM OR LEASE NAME
NAME OF OPERATOR		Inexco Federal
Quinoco Petroleum, Inc.	RECEIVED	/
P.O. Box 378111 Denver, CO 80237 LOCATION OF WELL (Report location clearly and in accordance with any 1	State requirements.*	10. FIBLD AND POOL, OR WILDCAT
See also space if belowly	FEB 29 '88	Burton flat mb
At surface		11. SBC., 2., BC, M., OR BLE. AND SUBVEY OR ARBA
1650'FSL&660'FEL	Э. С. Э.	12-T21S-R26E
15. BLEVATIONS (Show whether DP.	IT, GR. etc.)	12. COUNTY OR PARISE 13. STATE
3194.7' GR 3210.7'		Eddy NM
CL L A manuata Box To Indicate N	lature of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO :	BUBBEQ	UENT REPORT OF:
	WATER SHUT-OFF	BEPAIRING WELL
TEST WATER SHUT-OFF PULL OR ALTER CASING	PRACTURE TREATMENT	ALTERING CASING
PRACTURE TREAT	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL CHANGE PLANS	(Other)	a of multiple completion on Well
(Other) (Other) (DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertine) proposed work. If well is directionally drilled, give subsurface loca	Completion or Recou	Dietion Report and Log total
1. Circ hole w/ 9.5 ppg mud		
 Set CIBP @ 10,875' + 25 sx cmt. Cut and pull 5-1/2" csg @ 4,318' 100' cmt from 4,368'-4,268' 45 sx cmt @ 2,600' 		
 3. Cut and pull 5-1/2" csg @ 4,318' 4. 100' cmt from 4,368'-4,268' 5. 45 sx cmt @ 2,600' 6. 200' cmt from 200' to surface. 		
 3. Cut and pull 5-1/2" csg @ 4,318' 4. 100' cmt from 4,368'-4,268' 5. 45 sx cmt @ 2,600' 	ocation for approval	
 3. Cut and pull 5-1/2" csg @ 4,318' 4. 100' cmt from 4,368'-4,268' 5. 45 sx cmt @ 2,600' 6. 200' cmt from 200' to surface. 	ocation for approval	
 3. Cut and pull 5-1/2" csg @ 4,318' 4. 100' cmt from 4,368'-4,268' 5. 45 sx cmt @ 2,600' 6. 200' cmt from 200' to surface. 7. Set P&A marker and recondition 1 		$\frac{1}{2} = \frac{1}{2}$
 3. Cut and pull 5-1/2" csg @ 4,318' 4. 100' cmt from 4,368'-4,268' 5. 45 sx cmt @ 2,600' 6. 200' cmt from 200' to surface. 7. Set P&A marker and recondition 1 18. I hereby certify that the foregoing is true and correct SIGNED Acting Acting Machine IIILE		$\frac{1}{2} = \frac{1}{2}$
 3. Cut and pull 5-1/2" csg @ 4,318' 4. 100' cmt from 4,368'-4,268' 5. 45 sx cmt @ 2,600' 6. 200' cmt from 200' to surface. 7. Set P&A marker and recondition 1 18. I bereby certify that the foregoing is true and correct SIGNED Any Antomication State office use)		С. С
 3. Cut and pull 5-1/2" csg @ 4,318' 4. 100' cmt from 4,368'-4,268' 5. 45 sx cmt @ 2,600' 6. 200' cmt from 200' to surface. 7. Set P&A marker and recondition 1 18. I hereby certify that the foregoing is true and correct SIGNED Acting Acting Machine IIILE		$\frac{1}{2} = \frac{1}{2}$

I

surface restolution to congressed Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of th United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.