

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.O.B.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

AUG 7 1979

Form C-103
Revised 10-1-78

O. C. C.
ARTESIA, OFFICE

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
K5090 & K6598

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. Unit Agreement Name
2. Name of Operator	8. Firm or Lease Name
Howard Boatright Co., Inc. ✓	JCW State Com
3. Address of Operator	9. Well No.
P. O. Box 7251 - Odessa, Texas 79760	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER 0 1980 FEET FROM THE East LINE A 660 FEET FROM THE South LINE, SECTION 2 TOWNSHIP 20S RANGE 28E N.M.P.M.	Winchester - Morrow
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
3271.5 GR.	Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING O.N.S. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1109. 13 7/8 400-350 8 5/8 2701-1000 4 1/2 11334-575 TOC 9020 temporary

- Set cement retainer at 9800' and squeeze 50 sacks of cement below retainer
- Unsting and circulate hole with 9.5# Mud ladden fluid.
- Cut 4 1/2" Casing at free point. Pull out of hole with 4 1/2" Casing. approx. 9000
- Run tubing to stub and pump 35 sack plug and wait on cement.
- Tag Plug.
- Pull tubing up hole and spot plug at:
 - 7100 - 7200 - 35 sacks
 - 4650 - 4750 - 35 sacks 35470-1
 - 2650 - 2750 - 50 sacks - WOC and Tag
 - 350 - 450 - 35 sacks
- Cut off wellhead install dry hole marker and rig down.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W.C. Boatright TITLE President DATE August 6, 1979

APPROVED BY W.A. Gressett TITLE SUPERVISOR, DISTRICT II DATE AUG 8 1979

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness

Plugging