WELL

NAME OF OPERATOR

3. ADDRESS OF OPERATOR

GAS WELL

Cities Service Oil Company /

Box 1919 - Midland, Texas

1.

## L'TED STATES SUBMIT I OF THE INTERIOR (Other Interior verse side)

SUBMIT IN TR CATE\*
(Other instruction re-

o. c. c.

ARTESIA, DFFICE

Form approved.
Budget Bureau No. 42-R1424.
LEASE DESIGNATION AND SERIAL NO.
NM 26821

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

CEOL	OCICAL	SURVEY
GEOL	UGILAL	SURVEI

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such properise CEIVE

	원취실 환경 그는 기업 기업
9	
	7. UNIT AGREEMENT NAME
•	8. FARM OR LEASE NAME. Loafer Draw B
	9. WELL NO. 2 8 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4
	10. FIELD AND POOL, OR WILDCAT WILDCAT WILDCAT
	11. SEC., T., S., M., OR BLK. AND

1980'FNL & 860'FWL of Sec. 17-T21S-R22E, Eddy Co., New Mexico

<u> 1</u>503' GR

Sec. 17-T21S-R22E

14. PERMIT NO. | 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)

At surface

OTHER Dry Hole

12. COUNTY OR PARISH 18. STATE

Eddy New Mexico

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOT	ICE O	FINTENTION TO:			SUE	SEQUE	NT REPORT	OF:	17 10	•••
			r	- I					- 1 <u>1</u>	الجسار
TEST WATER SHUT-OFF	<b> </b>	PULL OR ALTER CASING		_	WATER SHUT-OFF			REPAIRING	WELL	
FRACTURE TREAT		MULTIPLE COMPLETE			FRACTURE TREATMENT		ou 🎋	ALTERING	CASING	
SHOOT OR ACIDIZE		ABANDON*	X	_	SHOOTING OR ACIDIZING		- 78	ABANDONM	ENT.	4
REPAIR WELL		CHANGE PLANS			(Other)		<u> 1                                   </u>		-	- 1
(Other)					(Norm: Report recompletion or Rec	sults of omplet	f multiple ion Report	completion and Log f	on Wel	IC ?

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and some pertinent to this work.)\*

T.D. 8591' Shale. We propose to plug and abandon this well in the following manner:

- 1. Spot a 50 sack cement plug across top of Morrow @ approx. 8175 8025 .
- 2. Spot a 50 sack cement plug across top of Strawn @ approx. 7560 7410.
- 3. Spot a 50 sack cement plug across top of Wolfcamp @ approx. 5150 50001
- 4. Spot a 35 sack cement plug across top of Abo @ approx. 3690 3590'.
- 5. Spot a 35 sack cement plug across top of Tubb @ approx. 3100 3000'.
- 6. Spot a 35 sack cement @ approx. 1850 1750' (1/2 in and 1/2 out of 8-5/8" casing seat @ 1800').
- 7. Set a 10 sack cement surface plug @ approx. 58 0' and install a h" dry hole marker.

This plugging procedure was given verbal approval by Mr. Leon Beekman with your Artesia, New Mexico office.

RECEIVED

JAN 2 6 1976

U. S. GEOLOGICAL SURVEY
ARTESIA NEW MEXICO

	ANIESIA NEW	MEYICOL
18. I hereby certify that the foregoing is true and correct		A SERBI LE SEE
SIGNED Effection	TITLE Region Operation Manager	DATE January 23, 1976
(This space for Federal or State office use)		
(This space for Federal of State outer use)		The state of the s
APPROVED BY CONSULTIONS OF APPROVAL, IF ANY:	TITLE	DATE
- COMMITTIONS OF APPROVAL, IF ANI:		

\*See Instructions on Reverse Side

APPROVED BY APPROVAL, IN ACTING DISTRICT ENGINEER