form 3160-5 June 1990)	RECEIVED	UNITED STATES PARTMENT OF THE INTERIOR	RECEIVED	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
	BUI	REAU OF LAND MANAGEMENT	SEP - ( 1993	5. Lease Designation and Serial No. NM-13624
الالم ایل Do not	and the same and the	NOTICES AND REPORTS ON WE osals to drill or to deepen or reentry attion FOR PERMIT—" for such pro	to a different poortion.	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE				7. If Unit or CA, Agreement Designation
1. Type of Well Oil Well Well Other				8. Well Name and No.
2. Name of Operator  Bonneville Fuels Corporation				Avalon Federal #1  9. API Well No.
3. Address and Telephone No.  1660 Lincoln, Suite 1800, Denver, CO 80264 (303) 863-1555				3001521814  10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Burton Flat, Morrow 11. County or Parish, State
		The, out the		Eddy, NM
12.	CHECK APPROPR	IATE BOX(s) TO INDICATE NATU	RE OF NOTICE, REPO	RT, OR OTHER DATA
	TYPE OF SUBMISSIO		TYPE OF ACTION	
	Notice of Intent	Abandonine Recompletic		Change of Plans  New Construction
	Subsequent Report	Plugging Ba		Non-Routine Fracturing Water Shut-Off
	Final Abandonment Not	Other		Conversion to Injection  Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)
give Bonne	subsurface locations and measi	ons (Clearly state all pertinent details, and give pertinent dured and true vertical depths for all markers and zones on the state of t		
	1) Set pkr @ 10 the Atoka.	780 above Morrow perfs with	knockout disk, to	isolate Morrow zone from
	the Atoka.		<u> </u>	
		he Atoka zone 10,724-30, 10,	416-22 with 4 spf.	
	<ul><li>2) Perforate t</li><li>3) Breakdown p</li></ul>	he Atoka zone 10,724-30, 10, erfs as necessary.		
	<ul><li>2) Perforate t</li><li>3) Breakdown p</li></ul>	he Atoka zone 10,724-30, 10,		osition, on tubing.
	<ul><li>2) Perforate t</li><li>3) Breakdown p</li></ul>	he Atoka zone 10,724-30, 10, erfs as necessary. inger and sliding sleeve ass		osition, on tubing.
	<ol> <li>Perforate t</li> <li>Breakdown p</li> <li>TIH with st</li> <li>Sting into</li> <li>Knock out k</li> </ol>	he Atoka zone 10,724-30, 10, erfs as necessary. inger and sliding sleeve ass pkr @ 10,780 mockout disk in pkr.	sembly, in closed p	osition, on tubing.
	2) Perforate to 3) Breakdown post 4) TIH with st 5) Sting into 6) Knock out k 7) Produce Ato	he Atoka zone 10,724-30, 10, erfs as necessary. inger and sliding sleeve ass pkr @ 10,780 mockout disk in pkr.	sembly, in closed p	osition, on tubing.
14. I hereby Signed	<ol> <li>Perforate t</li> <li>Breakdown p</li> <li>TIH with st</li> <li>Sting into</li> <li>Knock out k</li> </ol>	he Atoka zone 10,724-30, 10, erfs as necessary. inger and sliding sleeve ass pkr @ 10,780 cnockout disk in pkr.	sembly, in closed p	osition, on tubing.  Date 8/16/93